



TOYOTA AURIS: 1PSJ517

Vinnumber:	SB1MS3JE50E280741	Versionname:	1.8 HYBRID LOUNGE CVT AUTO
First Registrationdate:	6/09/2016	Fiscalpower:	
Expertise Mileage:	9571	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Hybrid Petrol	Oil level	OK
Maintenance	OK	Parking lot	4701
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	225/45/17/91 W LightMetal			
	Fr.L.	Dunlop: 7 mm	Fr.R.	Dunlop: 7 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	748,55
Tyre F R, Tear, E - Replace	132,00



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Door R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), E - Replace	235,20
---	--------



Door F R, Dent(s), LI - Repair and paint (complete)	318,35
---	--------

