

AH8IJA

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	170938 KM
File nr. :	1378291	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DDI331 / WAUZZZ8X9CB231679 /		yr of constructionr :	/
E-File nr. :		First registration :	16/04/2012
VFS-nr. :		Color :	PURPLE
Make + Model :	AUDI / A1	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ILOMAR NV	Co2:	110g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A1 BER Attraction S-tr.90PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Automaat algemeen	Number of places:	4
Number of gears:		Number of doors:	3
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK
Jack, wheelspanner :		Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	1.6-2 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	1.6-2 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	[x]	/	Rim :			/	Hubcap :	
	[x]		Width		Height		Type		Rim		Index	
	Front tyre		200		55		R		15		WINTER H	
	Rear tyre		200		55		R		15		WINTER H	
Remark :	REPSET OK											

Remark : REPSET OK

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :
	[x]	Width	Height	Type	Rim	Index
Front tyre		0	0	R	0	
Rear tyre		0	0	R	0	

Remark :

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	FRONT DOOR/LEFT/REAR	OTHER DAMAGES	
[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE	HERSTELD
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER		DENT			
		Repair paint - LI	New paint - E	Depr.	Total	
2	15 LU =72.00 EUR	169.44 EUR		50 %	241.44 EUR	
[x]	REAR MUDGUARD/LEFT/CENTER		OTHER DAMAGES		SLECHTE HERSTELLING/MAT	
	Number	Code	Description	Unit price	Depr.	Total
0	0					

Interior

[x]	ROOF UPHOLSTERY	OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	0 EUR		50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	SUN VISOR	120.00 EUR	50 %	120.00 EUR

1	2	3	4	5	6	7	8	9	10
120.00	241.44	0	0	0	0	0	0	0	0
60.00	120.72	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	361.44	0	361.44
HOG: 0	BG: 1		NA Deprec. 180.72
			0.00%
			TOTAL 180.72

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : ZONNEKLEP BLIJFT NIET MEER IN POSITIE STAAN [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 05/04/2017 Hour : 11:06 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	