

ASKUDT

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	100647 KM
File nr. :	1387142	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EVN507 / WAUZZZ8T9DA066253 /		yr of constructionr :	2013 / 00
E-File nr. :		First registration :	01/04/2013
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / A5 SPORTBACK	Fuel type :	DIESEL
Object nr. :	73166	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Crelan NV	Co2:	118g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	3 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	A5 SB TDie DPF 163PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1968
Gear box :	Manueel	Number of places:	4
Number of gears:	6	Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
	Warning triangle : OK [x]
First aid kit : OK [x]	Oil level : OK [x]
Jack, wheelspanner :	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	4-6 /	Rim :	/
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50		17	Y
Rear tyre	225	50		17	Y

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
2	0	LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR
[x]	REAR DOOR/RIGHT/FRONT		DENT		MET LAKSCHADE, 10 STUKS	
			Repair paint - LI	New paint - E	Depr.	Total
3	0	LU =0.00 EUR	382.02 EUR		50 %	382.02 EUR
[x]	FRONT DOOR/RIGHT/REAR		DENT		3 STUKS	
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT BUMPER/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
1	0	LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

1	2	3	4	5	6	7	8	9	10
254.16	254.16	382.02	63.00	0	0	0	0	0	0
127.08	127.08	191.01	63.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	890.34	0	953.34
HOG: 0	BG: 2		NA Deprec. 508.17
			0.00%
			TOTAL 508.17

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 11/04/2017 Hour : 11:55 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	