

ATUULE

☒ EFFECTIVE    ☐ NOT EXECUTED    ☒ COLLECTION    ☐ DELIVERY

[x] = Status Modification

|                               |                                         |                          |                               |
|-------------------------------|-----------------------------------------|--------------------------|-------------------------------|
| Commissionar :                | KBC REMARKETING                         | Cleanliness :            | INT: CLEAN [x] EXT: DIRTY [x] |
| Owner :                       |                                         | Mileage :                | 104420 KM                     |
| File nr. :                    | 1388098                                 | Mileage start / arrival: | 0 / 0                         |
| Reg number / Chassis / Ref :  |                                         | Mileag ref. service :    | 0                             |
| 1FOV076 / WAUZZZ8X1EB016185 / |                                         | yr of constructionr :    | 2013 / 00                     |
| E-File nr. :                  |                                         | First registration :     | 10/09/2013                    |
| VFS-nr. :                     |                                         | Color :                  | SILVER                        |
| Make + Model :                | AUDI / A1 SPORTBACK                     | Fuel type :              | DIESEL                        |
| Object nr. :                  | 32588                                   | Fuel :                   |                               |
| Classification :              |                                         | Environment Class:       | EURO 5                        |
| Customer company :            | ERNST & YOUNG<br>BEDRIJFSREVISOREN CVBA | Co2:                     | 99g/km                        |
| Driver :                      |                                         | Remote controls:         | 2                             |
| Covering :                    | TISSUE                                  | Number keys :            | 2 [x]                         |
| Vehicle kind :                |                                         | Seats (minivan) :        | 0                             |
| Vehicle type :                | A1 SB Attraction 105PK                  | Country registration :   | BELGIUM                       |

|                              |         |                     |         |
|------------------------------|---------|---------------------|---------|
| VAT over the margin - car:   | No      | Metallic paint:     | Yes     |
| Variant car:                 |         | Engine size:        | 1598    |
| Gear box :                   | Manueel | Number of places:   | 4       |
| Number of gears:             | 5       | Number of doors:    | 5       |
| HP:                          | 105     | kW:                 | 77      |
| Fisc HP                      |         | Imported vehicle:   |         |
| Animals transported:         |         | Smoked in vehicle:  |         |
| Due date vehicle inspection: |         | Extra set of tires: |         |
|                              |         | Use:                | Unknown |
| General condition:           |         |                     |         |

|                              |    |                  |                         |        |
|------------------------------|----|------------------|-------------------------|--------|
| Original registr. number :   | OK | Service manual : | OK                      | [x]    |
| Cert. of reg. / Part 1:      | OK | [x]              | Cert. of conformity :   | OK     |
| Cert. of reg. copy / Part 2: |    |                  | Insurance certificate : |        |
| Warning vest :               |    |                  | Transport licence :     |        |
| Tax certificate :            |    |                  | Navigation CD/SD/DVD    |        |
| Fuel card :                  |    |                  | Car radio :             | OK [x] |
| Mobile phone kit :           |    |                  | Extinguisher :          | OK [x] |
|                              |    |                  | Warning triangle :      | OK [x] |
| First aid kit :              | OK | [x]              | Oil level :             | OK [x] |
| Jack, wheelspanner :         |    |                  | Filled up :             | 0      |

## Wheels and tyres: Summer tires

|            |     |             |        |     |     |       |       |       |                 |                 |          |          |
|------------|-----|-------------|--------|-----|-----|-------|-------|-------|-----------------|-----------------|----------|----------|
| Wheel FL:  | [x] | CONTINENTAL | Tyre : | OK  | [x] | 2-4 / | Rim : | [x]   | WHEEL SCRATCHED | /               | Hubcap : |          |
| Wheel RL : | [x] | CONTINENTAL | Tyre : | OK  | [x] | 2-4 / | Rim : | [x]   | WHEEL SCRATCHED | /               | Hubcap : |          |
| Wheel FR : | [x] | CONTINENTAL | Tyre : | [x] | OK  | [x]   | 2-4 / | Rim : | [x]             | WHEEL SCRATCHED | /        | Hubcap : |
| Wheel RR : | [x] | CONTINENTAL | Tyre : | OK  | [x] | 2-4 / | Rim : | [x]   | WHEEL SCRATCHED | /               | Hubcap : |          |
| Wheel RES: | [x] |             | Tyre : | OK  |     | /     | Rim : |       |                 | /               | Hubcap : |          |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205   | 55     | R    | 15  | V     |
| Rear tyre  | 205   | 55     | R    | 15  | V     |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |  |   |          |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL:  |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RL : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel FR : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RR : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RES: |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

|     |                                     |                           |           |
|-----|-------------------------------------|---------------------------|-----------|
| [x] | REAR MUDGUARD/LEFT/FRONT            | SCRATCH WITH PAINT DAMAGE |           |
| [x] | FRONT DOOR/RIGHT/CENTER             | SCRATCH WITH PAINT DAMAGE | ENKELE    |
| [x] | WINDOW STYLE/FRONT DOOR/RIGHT/FRONT | SCRATCH WITH PAINT DAMAGE |           |
| [x] | FRONT BUMPER/RIGHT/SIDE             | SCRATCH WITH PAINT DAMAGE | L+R       |
| [x] | ROOF/CENTER/LEFT                    | OTHER DAMAGES             | INWERKING |

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

|     |                           |              |                           |               |                     |            |
|-----|---------------------------|--------------|---------------------------|---------------|---------------------|------------|
| [x] | REAR BUMPER/CENTER/LEFT   |              | SCRATCH WITH PAINT DAMAGE |               |                     |            |
|     |                           |              | Repair paint - LI         | New paint - E | Depr.               | Total      |
| 4   | 0                         | LU =0.00 EUR | 169.44 EUR                |               | 50 %                | 169.44 EUR |
| [x] | REAR MUDGUARD/RIGHT/FRONT |              | SCRATCH WITH PAINT DAMAGE |               |                     |            |
|     |                           |              | Repair paint - LI         | New paint - E | Depr.               | Total      |
| 5   | 0                         | LU =0.00 EUR | 246.56 EUR                |               | 50 %                | 246.56 EUR |
| [x] | REAR DOOR/LEFT/CENTER     |              | SCRATCH WITH PAINT DAMAGE |               |                     |            |
|     |                           |              | Repair paint - LI         | New paint - E | Depr.               | Total      |
| 3   | 0                         | LU =0.00 EUR | 254.68 EUR                |               | 50 %                | 254.68 EUR |
| [x] | REAR DOOR/RIGHT/REAR      |              | OTHER DAMAGES             |               | SLECHTE HERSTELLING |            |
|     | Number                    | Code         | Description               | Unit price    | Depr.               | Total      |
| 0   | 0                         |              |                           |               |                     |            |
| [x] | FRONT MUDGUARD/RIGHT/REAR |              | SCRATCH WITH PAINT DAMAGE |               |                     |            |
|     |                           |              | Repair paint - LI         | New paint - E | Depr.               | Total      |
| 6   | 0                         | LU =0.00 EUR | 176.14 EUR                |               | 50 %                | 176.14 EUR |
| [x] | BONNET/CENTER/RIGHT/FRONT |              | SCRATCH WITH PAINT DAMAGE |               |                     |            |
|     |                           |              | Repair paint - LI         | New paint - E | Depr.               | Total      |
| 2   | 0                         | LU =0.00 EUR | 232.06 EUR                |               | 50 %                | 232.06 EUR |

## Others

RIM REAR LEFT

| Number | Code | Description       | Unit price         | Depr.     | Total     |
|--------|------|-------------------|--------------------|-----------|-----------|
| 7      | I 1  | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

RIM REAR RIGHT

| Number | Code | Description       | Unit price         | Depr.     | Total     |
|--------|------|-------------------|--------------------|-----------|-----------|
| 7      | I 1  | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

RIM FRONT RIGHT

| Number | Code | Description       | Unit price         | Depr.     | Total     |
|--------|------|-------------------|--------------------|-----------|-----------|
| 7      | I 1  | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

| 1 | 2      | 3      | 4      | 5      | 6      | 7      | 8 | 9 | 10 |
|---|--------|--------|--------|--------|--------|--------|---|---|----|
| 0 | 232.06 | 254.68 | 169.44 | 246.56 | 176.14 | 285.00 | 0 | 0 | 0  |
| 0 | 116.03 | 127.34 | 84.72  | 123.28 | 88.07  | 285.00 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                   |
|------------|-------------|---------|-------------------|
| 285.00     | 1078.88     | 0       | 1363.88           |
| HOG: 0     | BG: 1       |         | NA Deprec. 824.44 |
|            |             |         | 0.00%             |
|            |             |         | TOTAL 824.44      |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|                               |                                  |                                 |
|-------------------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min            | Waiting time : 0 min<br>Reason : | Towing time : 0 min<br>Reason : |
| NOT EXECUTED : No<br>Reason : |                                  |                                 |
| Remark :                      |                                  |                                 |

## Prices in EUR without VAT

|                                                                                                                                                                      |                                |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|
| Authorized by customer :<br><br>Remark authorized customer :<br><br>Date : 12/04/2017      Hour : 13:28<br>Company :<br>Executed by VAB Fleet Services<br>E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br>                                              |                                |