

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	96640 KM
File nr. :	1387277	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GNZ766 / WBA3K110X0F831446 /		yr of constructionr :	/
E-File nr. :		First registration :	21/03/2014
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 3 TOURING	Fuel type :	
Object nr. :	33599	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ISS CATERING	Co2:	119g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	[x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
		Warning triangle :	OK [x]
First aid kit :	OK [x]	Oil level :	OK [x]
Jack, wheelspanner :		Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6 /	Rim :	/
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	H
Rear tyre	205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR BUMPER/CENTER/LEFT		SCRATCH (WITHOUT PAINT DAMAGE)		
	Number Code	Description	Unit price	Depr.	Total
0	0				
[x]	REAR MUDGUARD/LEFT/FRONT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
[x]	REAR DOOR/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	ROOF/CENTER/RIGHT		OTHER DAMAGES	CHEMISCHE INWERKING	
		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR
[x]	FRONT DOOR/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT MUDGUARD/LEFT/REAR		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR
[x]	BONNET/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR
[x]	FRONT BUMPER/LEFT		DENT		
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x] FRONT BUMPER/RIGHT DENT

Number	Code	Description	Unit price	Depr.	Total
0	0				

Interior

[x] CENTER CONSOLE OTHER DAMAGES

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR	0 EUR		50 %	
	Repair paint - LI	New paint - E	Depr.	Total
6 10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
6	1	GPS SCHERM	1200.00 EUR	50 %	1200.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	290.08	1165.08	211.80	481.50	1248.00	0	0	0	0
105.90	145.04	582.54	105.90	240.75	624.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	3608.26	0	3608.26
HOG: 0	BG: 0		NA Deprec. 1804.13
			0.00%
			TOTAL 1804.13

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 11/04/2017 Hour : 15:55 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	