

AR9XLH

☒ EFFECTIVE   
 ☐ NOT EXECUTED   
 ☒ COLLECTION   
 ☐ DELIVERY

[x] = Status Modification

|                               |                                |                          |                               |
|-------------------------------|--------------------------------|--------------------------|-------------------------------|
| Commissionar :                | KBC REMARKETING                | Cleanliness :            | INT: CLEAN [x] EXT: DIRTY [x] |
| Owner :                       |                                | Mileage :                | 125591 KM                     |
| File nr. :                    | 1386174                        | Mileage start / arrival: | 0 / 0                         |
| Reg number / Chassis / Ref :  |                                | Mileag ref. service :    | 0                             |
| 1ERM204 / WBA1C91020J508153 / |                                | yr of constructionr :    | /                             |
| E-File nr. :                  |                                | First registration :     | 01/03/2013                    |
| VFS-nr. :                     |                                | Color :                  | BLACK                         |
| Make + Model :                | BMW / 1 HATCH                  | Fuel type :              | DIESEL                        |
| Object nr. :                  | 67706                          | Fuel :                   |                               |
| Classification :              |                                | Environment Class:       | EURO 5                        |
| Customer company :            | EBA                            | Co2:                     | 99g/km                        |
| Driver :                      |                                | Remote controls:         | 2                             |
| Covering :                    | TISSUE                         | Number keys :            | 2 [x]                         |
| Vehicle kind :                | VEHICLE                        | Seats (minivan) :        | 0                             |
| Vehicle type :                | 1 HATCH 116d Eff.Dyn.Ed. 116PK | Country registration :   | BELGIUM                       |

|                              |         |                     |         |
|------------------------------|---------|---------------------|---------|
| VAT over the margin - car:   | No      | Metallic paint:     | Yes     |
| Variant car:                 |         | Engine size:        | 1596    |
| Gear box :                   | Manueel | Number of places:   | 5       |
| Number of gears:             | 6       | Number of doors:    | 5       |
| HP:                          | 116     | kW:                 | 85      |
| Fisc HP                      |         | Imported vehicle:   |         |
| Animals transported:         | No      | Smoked in vehicle:  | No      |
| Due date vehicle inspection: |         | Extra set of tires: | No      |
|                              |         | Use:                | Unknown |
| General condition:           |         |                     |         |

|                              |    |                       |                         |        |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number :   | OK | Service manual :      | OK                      | [x]    |
| Cert. of reg. / Part 1:      |    | Cert. of conformity : | OK                      |        |
| Cert. of reg. copy / Part 2: | OK | [x]                   | Insurance certificate : |        |
| Warning vest :               | OK | [x]                   | Transport licence :     |        |
| Tax certificate :            |    |                       | Navigation CD/SD/DVD    |        |
| Fuel card :                  |    |                       | Car radio :             | OK [x] |
| Mobile phone kit :           |    |                       | Extinguisher :          | OK [x] |
|                              |    |                       | Warning triangle :      | OK [x] |
| First aid kit :              | OK | [x]                   | Oil level :             | OK [x] |
| Jack, wheelspanner :         | OK | [x]                   | Filled up :             | 0      |

## Wheels and tyres: Winter tires

|            |     |        |        |     |     |       |       |       |          |
|------------|-----|--------|--------|-----|-----|-------|-------|-------|----------|
| Wheel FL:  | [x] | KLÉBER | Tyre : | OK  | [x] | 2-4 / | Rim : | /     | Hubcap : |
| Wheel RL : | [x] | KLÉBER | Tyre : | OK  | [x] | 2-4 / | Rim : | /     | Hubcap : |
| Wheel FR : | [x] | KLÉBER | Tyre : | [x] | OK  | [x]   | 2-4 / | Rim : | /        |
| Wheel RR : | [x] | KLÉBER | Tyre : | OK  | [x] | 2-4 / | Rim : | /     | Hubcap : |
| Wheel RES: | [x] |        | Tyre : | OK  |     | /     | Rim : | /     | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205   | 55     | R    | 16  | M+S   |
| Rear tyre  | 205   | 55     | R    | 16  | M+S   |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |   |          |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL:  |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: |  | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] BONNET/CENTER/LEFT DENT

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x] REAR BUMPER/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE

|                  | Repair paint - LI | New paint - E | Depr. | Total      |
|------------------|-------------------|---------------|-------|------------|
| 2 0 LU =0.00 EUR | 254.16 EUR        |               | 50 %  | 254.16 EUR |

[x] FRONT DOOR/LEFT/CENTER DENT

|                  | Repair paint - LI | New paint - E | Depr. | Total      |
|------------------|-------------------|---------------|-------|------------|
| 1 0 LU =0.00 EUR | 382.02 EUR        |               | 50 %  | 382.02 EUR |

| 1      | 2      | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|---|---|---|---|---|---|---|----|
| 382.02 | 254.16 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |
| 191.01 | 127.08 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                   |
|------------|-------------|---------|-------------------|
| 0          | 636.18      | 0       | 636.18            |
| HOG: 0     | BG: 2       |         | NA Deprec. 318.09 |
|            |             |         | 0.00%             |
|            |             |         | TOTAL 318.09      |

# APPRAISAL

**www.vabfleetservices.be**

**Date :** 07/04/2017

4/4

**[x] = Status Modification**


**Pictures :** No

## CIRCUMSTANCES

### UNDER CONDITION - DUSTY VEHICLE

|                    |                      |                     |
|--------------------|----------------------|---------------------|
| Extra Time : 0 min | Waiting time : 0 min | Towing time : 0 min |
|                    | Reason :             | Reason :            |
| NOT EXECUTED : No  |                      |                     |
| Reason :           |                      |                     |
| Remark :           |                      |                     |

**Prices in EUR without VAT**

|                                                                                                                                |                                |
|--------------------------------------------------------------------------------------------------------------------------------|--------------------------------|
| <b>Authorized by customer :</b>                                                                                                | Executed by VAB Fleet Services |
| <b>Remark authorized customer :</b>                                                                                            |                                |
| <b>Date :</b> 07/04/2017 <b>Hour :</b> 09:07                                                                                   |                                |
| <b>Company :</b><br><b>Executed by VAB Fleet Services</b><br><b>E-Mail :</b> @                                                 |                                |
| <b>Signature authorized by customer</b><br> |                                |