

A6359J

☒ EFFECTIVE ☐ NOT EXECUTED ☐ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	257951 KM
File nr. :	1369560	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1KAZ589 / VF7YCTMFC12621045 /		yr of constructionr :	2014 / 00
E-File nr. :		First registration :	22/05/2014
VFS-nr. :		Color :	WHITE
Make + Model :	CITROEN / JUMPER	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :	DELIVERY VAN C	Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	229g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	No
Variant car:		Engine size:	2198
Gear box :	Manueel	Number of places:	3
Number of gears:	6	Number of doors:	5
HP:	131	kW:	96
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	NOK			Service manual :	OK	☐
Cert. of reg. / Part 1:	OK	☐		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	☐		Insurance certificate :		
Warning vest :				Transport licence :		
Tax certificate :				Navigation CD/SD/DVD		
Fuel card :				Car radio :	OK	☐
Mobile phone kit :				Extinguisher :	OK	☐
				Warning triangle :	OK	☐
First aid kit :	OK	☐		Oil level :	OK	☐
Jack, wheelspanner :				Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL :	[x]	ANDERE	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :	
Wheel FR :	[x]	ANDERE	Tyre :	[x]	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

	[x]	Width	Height	Type	Rim	Index
Front tyre		215	70	R	15	T
Rear tyre		215	70	R	15	T

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
5	20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR
[x]	REAR MUDGUARD/LEFT/FRONT	DENT		ENKELE	
		Repair paint - LI	New paint - E	Depr.	Total
4	10 LU =48.00 EUR	231.15 EUR			279.15 EUR
[x]	REAR MUDGUARD/RIGHT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
6	30 LU =144.00 EUR	231.15 EUR		50 %	375.15 EUR
[x]	REAR DOOR/RIGHT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
6	30 LU =144.00 EUR	238.76 EUR		50 %	382.76 EUR
[x]	FRONT THRESHOLD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	10 LU =48.00 EUR	232.88 EUR		50 %	280.88 EUR
[x]	FRONT DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	15 LU =72.00 EUR	238.76 EUR		50 %	310.76 EUR
[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	1 I 1 i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
[x]	FRONT DOOR/RIGHT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
6	30 LU =144.00 EUR	0 EUR	326.78 EUR	50 %	470.78 EUR
[x]	FRONT THRESHOLD/RIGHT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
6	40 LU =192.00 EUR	0 EUR	310.50 EUR	50 %	502.50 EUR

[x]	FRONT MUDGUARD/RIGHT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
6	20 LU =96.00 EUR	0 EUR	177.91 EUR	50 %	273.91 EUR
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
2	20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	BROKEN / CRACKED			
		Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR	0 EUR		50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	FRONT BUMPER	302.40 EUR	50 %	302.40 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	REAR BUMPER	257.40 EUR	50 %	257.40 EUR
Number	Code	Description	Unit price	Depr.	Total
6	1	DOOR FR	377.10 EUR	50 %	377.10 EUR
Number	Code	Description	Unit price	Depr.	Total
6	1	DOORSTEP	187.50 EUR	50 %	187.50 EUR
Number	Code	Description	Unit price	Depr.	Total
6	1	FENDER FR	129.60 EUR	50 %	129.60 EUR
Number	Code	Description	Unit price	Depr.	Total
7	1	MIRROR	120.00 EUR	50 %	120.00 EUR

1	2	3	4	5	6	7	8	9	10
58.80	398.40	591.64	279.15	353.40	2699.30	120.00	0	0	0
58.80	199.20	295.82	279.15	176.70	1349.65	60.00	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
58.80	4441.89	0	4500.69
HOG: 0	BG: 3		NA Deprec. 2419.32
			0.00%
			TOTAL 2419.32

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 16/02/2017 Hour : 12:03 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	