

ATL8YZ

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	55903 KM
File nr. :	1387889	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GXC615 / VF73A9HC8EJ635323 /		yr of constructionr :	2014 / 00
E-File nr. :		First registration :	23/05/2014
VFS-nr. :		Color :	RED
Make + Model :	CITROEN / C4 PICASSO	Fuel type :	DIESEL
Object nr. :	42718	Fuel :	
Classification :	N	Environment Class:	EURO 5
Customer company :	COMMISSIE VOOR REGULERING VAN ELECTRICIT	Co2:	105g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	7 [x]
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1560
Gear box :	Automaat algemeen	Number of places:	7
Number of gears:		Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:			Insurance certificate :	
Warning vest :			Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	50	R	17	M+S
Rear tyre	215	50	R	17	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
5	20 LU =96.00 EUR	211.80 EUR		50 %	307.80 EUR
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
[x]	REAR DOOR/RIGHT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
8	30 LU =144.00 EUR	0 EUR	435.72 EUR	50 %	579.72 EUR
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
8	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	BONNET/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR
[x]	FRONT BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x]	ROOF/CENTER/LEFT	OTHER DAMAGES	INWERKING	
		Repair paint - LI	New paint - E	Depr. Total
3	0 LU =0.00 EUR	481.50 EUR	50 %	481.50 EUR
[x]	REAR DOOR/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr. Total
6	0 LU =0.00 EUR	301.68 EUR	50 %	301.68 EUR

Others

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
9	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
9	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
9	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
5	1 MISTLAMP		60.00 EUR	50 %	60.00 EUR
Number	Code	Description	Unit price	Depr.	Total
8	1 DOOR REAR RIGHT		367.20 EUR	50 %	367.20 EUR

1	2	3	4	5	6	7	8	9	10
290.08	211.80	481.50	308.20	367.80	301.68	308.20	1265.27	285.00	0
145.04	105.90	240.75	154.10	183.90	150.84	154.10	632.64	285.00	0

INNOVATIVE	TRADITIONAL	GENERAL	
285.00	3534.53	0	3819.53
HOG: 0	BG: 0		NA Deprec. 2052.26
			0.00%
			TOTAL 2052.26

APPRAISAL

www.vabfleetservices.be

Date : 12/04/2017

5/5

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min	Towing time : 0 min
	Reason :	Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 12/04/2017 Hour : 12:22	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	