

9GD906

☒ EFFECTIVE    ☐ NOT EXECUTED    ☐ COLLECTION    ☐ DELIVERY

[x] = Status Modification

|                              |                 |                          |                               |
|------------------------------|-----------------|--------------------------|-------------------------------|
| Commissionar :               | KBC REMARKETING | Cleanliness :            | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner :                      |                 | Mileage :                | 55940 KM                      |
| File nr. :                   | 1349613         | Mileage start / arrival: | 0 / 0                         |
| Reg number / Chassis / Ref : |                 | Mileag ref. service :    | 0                             |
| JG8482 / WAUZZZ8U4ER095641 / |                 | yr of constructionr :    | /                             |
| E-File nr. :                 |                 | First registration :     | 28/05/2014                    |
| VFS-nr. :                    |                 | Color :                  | SILVER                        |
| Make + Model :               | AUDI / Q3       | Fuel type :              | DIESEL                        |
| Object nr. :                 | ONBEKEND        | Fuel :                   |                               |
| Classification :             |                 | Environment Class:       |                               |
| Customer company :           | ONBEKEND        | Co2:                     | g/km                          |
| Driver :                     |                 | Remote controls:         | 2                             |
| Covering :                   | LEATHER         | Number keys :            | 2 [x]                         |
| Vehicle kind :               | VEHICLE         | Seats (minivan) :        | 0                             |
| Vehicle type :               |                 | Country registration :   | BELGIUM                       |

|                              |         |                     |         |
|------------------------------|---------|---------------------|---------|
| VAT over the margin - car:   |         | Metallic paint:     | Yes     |
| Variant car:                 | SUV     | Engine size:        | 1968    |
| Gear box :                   | Manueel | Number of places:   | 5       |
| Number of gears:             | 6       | Number of doors:    | 5       |
| HP:                          | 177     | kW:                 | 130     |
| Fisc HP                      |         | Imported vehicle:   |         |
| Animals transported:         | No      | Smoked in vehicle:  | No      |
| Due date vehicle inspection: |         | Extra set of tires: | No      |
|                              |         | Use:                | Unknown |
| General condition:           |         |                     |         |

|                              |     |                  |                         |                    |
|------------------------------|-----|------------------|-------------------------|--------------------|
| Original registr. number :   | OK  | Service manual : | OK                      | [x]                |
| Cert. of reg. / Part 1:      | OK  | [x]              | Cert. of conformity :   | NOK                |
| Cert. of reg. copy / Part 2: |     |                  | [x]                     | MISSING/INCOMPLETE |
| Warning vest :               | NOK | [x]              | Insurance certificate : |                    |
| Tax certificate :            |     |                  | Transport licence :     |                    |
| Fuel card :                  |     |                  | Navigation CD/SD/DVD    |                    |
| Mobile phone kit :           |     |                  | Car radio :             | OK                 |
|                              |     |                  | [x]                     |                    |
|                              |     |                  | Extinguisher :          | OK                 |
|                              |     |                  | [x]                     |                    |
| First aid kit :              | OK  | [x]              | Warning triangle :      | OK                 |
|                              |     |                  | [x]                     |                    |
| Jack, wheelspanner :         | OK  | [x]              | Oil level :             | OK                 |
|                              |     |                  | [x]                     |                    |
|                              |     |                  | Filled up :             | 0                  |

## Wheels and tyres: Winter tires

|            |     |        |        |     |     |       |       |          |          |
|------------|-----|--------|--------|-----|-----|-------|-------|----------|----------|
| Wheel FL:  | [x] | DUNLOP | Tyre : | OK  | [x] | 2-4 / | Rim : | /        | Hubcap : |
| Wheel RL : | [x] | DUNLOP | Tyre : | OK  | [x] | 2-4 / | Rim : | /        | Hubcap : |
| Wheel FR : | [x] | DUNLOP | Tyre : | [x] | OK  | [x]   | 2-4 / | Rim :    | /        |
|            |     |        |        |     |     |       |       | Hubcap : |          |
| Wheel RR : | [x] | DUNLOP | Tyre : | OK  | [x] | 2-4 / | Rim : | /        | Hubcap : |
| Wheel RES: | [x] |        | Tyre : | OK  |     | /     | Rim : | /        | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 235   | 55     | R    | 18  | M+S   |
| Rear tyre  | 235   | 55     | R    | 18  | M+S   |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |   |          |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL:  |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: |  | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

|     |                            |                                |
|-----|----------------------------|--------------------------------|
| [x] | REAR MUDGUARD/LEFT/REAR    | SCRATCH WITH PAINT DAMAGE      |
| [x] | REAR MUDGUARD/RIGHT/CENTER | SCRATCH (WITHOUT PAINT DAMAGE) |
| [x] | BONNET/CENTER/RIGHT/FRONT  | CHIPS                          |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|---|---|---|---|---|---|---|---|---|----|
| 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |
| 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |              |
|------------|-------------|---------|--------------|
| 0          | 0           | 0       | 0            |
| HOG: 0     | BG: 0       |         | NA Deprec. 0 |
|            |             |         | 0.00%        |
|            |             |         | TOTAL 0      |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|                               |                                  |                                 |
|-------------------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min            | Waiting time : 0 min<br>Reason : | Towing time : 0 min<br>Reason : |
| NOT EXECUTED : No<br>Reason : |                                  |                                 |
| Remark :                      |                                  |                                 |

## Prices in EUR without VAT

|  |                                |
|--|--------------------------------|
| Authorized by customer :<br><br>Remark authorized customer :<br><br>Date : 19/12/2016      Hour : 13:19<br>Company :<br>Executed by VAB Fleet Services<br>E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br>   |                                |