

AS1HPB

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	89157 KM
File nr. :	1386733	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ESK287 / WF0KXXGCBKDJ60996 /		yr of constructionr :	/
E-File nr. :		First registration :	08/03/2013
VFS-nr. :		Color :	BLUE
Make + Model :	FORD / FOCUS CLIPPER	Fuel type :	DIESEL
Object nr. :	64040	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	88g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	FOCUS BER EConetic Trend 88g 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	[x]
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
		Warning triangle :	OK
First aid kit :	OK	Oil level :	OK
Jack, wheelspanner :		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	ANDERE	Tyre :	OK	4-6 /	Rim :	/	Hubcap :	
Wheel RL :	ANDERE	Tyre :	OK	4-6 /	Rim :	/	Hubcap :	SCRATCHED
Wheel FR :	ANDERE	Tyre :	OK	4-6 /	Rim :	/	Hubcap :	BROKEN / CRACKED
Wheel RR :	ANDERE	Tyre :	OK	4-6 /	Rim :	/	Hubcap :	
Wheel RES:	ANDERE	Tyre :	OK	/	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	W
Rear tyre	205	55	R	16	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR DOOR/LEFT/FRONT	DENT	
[x]	THRESHOLD FRONT/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	BINNEN
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT MUDGUARD/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS	

Interior

CENTER CONSOLE	SCRATCHED
DOOR IN REAR L	OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE		SPOILER	
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]	REAR DOOR/LEFT/CENTER		OTHER DAMAGES		RUBBER IS LOS	
			Repair paint - LI	New paint - E	Depr.	Total
8	5 LU =24.00 EUR		0 EUR		50 %	24.00 EUR
[x]	REAR DOOR/RIGHT/FRONT		DENT		MET LAKSCHADE // CARACTERLIJN	
			Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR		318.35 EUR		50 %	318.35 EUR
[x]	WINDSCREEN/CENTER/RIGHT		WINDOW DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
7	I 1	i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR

Interior

[x] SEAT FL STAIN

Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR	14.58 EUR

ROOF UPHOLSTERY BURNT

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-intvlr-02	SUPPL VELOURS REPAIR	18.00 EUR	18.00 EUR

Others

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR		50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
30.00	0	318.35	110.64	18.00	14.58	58.80	24.00	0	0
15.00	0	159.18	110.64	18.00	14.58	58.80	12.00	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
202.02	372.35	0	574.37
HOG: 0	BG: 0		NA Deprec. 388.20
			0.00%
			TOTAL 388.20

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/04/2017 Hour : 11:02 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	