

www.vabfleetservices.be Date: 21/12/2016 1/6

9AOONW

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Vehicle type:

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 31039 KM File nr. : Mileage start / arrival: 0 / 01345050 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1DVG677 / JTHBB262402041807 / E-File nr. : First registration: 07/09/2012 Color: VFS-nr.: **BLACK** Make + Model : Fuel type : LEXUS / IS **DIESEL** Object nr. : Fuel: Classification: **Environment Class:** EURO 5 Customer company: Co2: Magotteaux International sa 144g/km Driver : Remote controls: 2 LEATHER Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0

Country registration:

BELGIUM

IS 220d Luxury Pack 177PK

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	2231
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
нр:	177	kW:	130
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:	07/09/2017	Extra set of tires:	No
		Use:	Unknown
General condition:	,	l	



Date: 21/12/2016 www.vabfleetservices.be 2/6

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Fron	t tyre		225			4	15			R		17	W
		[x]	Width	Ì		Hei	ight			Туре		Rim	Index
Wheel RES:	[x]	ANDERE	Tyre:		OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel RR:	[x]	DUNLOP	Tyre:		OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel FR:	[x]	DUNLOP	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel RL:	[x]	DUNLOP	Tyre:		OK	[x]	4-6/	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel FL:	[x]	DUNLOP	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	

_	[]	7774411	110.8	- J P C		1114011
	Front tyre	225	45	R	17	W
	Rear tyre	225	45	R	17	W
_						

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
_					

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 21/12/2016 3/6



21/12/2016 www.vabfleetservices.be Date: 4/6

STATUS: ACCEPTABLE / USAGE DAMAGE

Boo	dywork \& windows		
[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/RIGHT/CENTER	DENT	
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT	
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	POLIR
[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE	POLIR
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	BORD PORTE
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	POLIR
[x]	FRONT MUDGUARD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	POLIR
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	
Acc	cessories and others		

OUTSIDE MIRROR LEFTHAND SIDE

SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Others

RIM FRO	ONT LEFT				
Number	Code	Description	Unit price	Depr.	Total
I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR
RIM REA	AR LEFT				
Number	Code	Description	Unit price	Depr.	Total
I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR
RIM REA	AR RIGHT				
Number	Code	Description	Unit price	Depr.	Total
I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR
RIM FRO	ONT RIGHT				
Number	Code	Description	Unit price	Depr.	Total
I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	1	95.00 EUR



www.vabfleetservices.be Date: 21/12/2016 5/6

1	2	3	4	5	6	7	8	9	10
380.00	0	0	0	0	0	0	0	0	0
380.00	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
380.00	0	0		380.00
HOG: 0	BG: 0		NA Deprec.	380.00
			0.00%	
			TOTAL	380.00



21/12/2016 Date: www.vabfleetservices.be 6/6

[x] = Status Modification

Pictures: No	1								
CIRCUMS'	TANCES		NORMAL CONCLU	NORMAL CONCLUSION					
Extra Time :	0 min	Waiting time: 0 m Reason:	in	Towing time : Reason :	0 min				
NOT EXECUTED :	No	I		ı					
Remark :									
Prices in EUR w	vithout VAT								
Authorized by customer:			Executed by VAB Fleet Se	ervices					
Remark authorized	customer :								
Date :	21/12/2016	Hour: 09:23							
Company :									
Executed by VAB Fl Services	leet								
E-Mail :	@								
Signature authorized	by customer								