

☒ EFFECTIVE ☐ NOT EXECUTED ☐ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	109914 KM
File nr. :	1383894	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
QW4836 / W0LPE9EN1D2072780 /		yr of constructionr :	/
E-File nr. :		First registration :	25/04/2013
VFS-nr. :		Color :	GREY
Make + Model :	OPEL / ZAFIRA	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	HP PSF LUXEMBOURG SARL - SBB1773477	Co2:	g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	ZAFIRA TOURER Cosmo 165PK Aut.	Country registration :	LUXEMBOURG

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1956
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	165	kW:	121
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity :
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest : OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
	Warning triangle : OK [x]
First aid kit : OK [x]	Oil level : OK [x]
Jack, wheelspanner :	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	2-4 /	Rim :	/
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	H
Rear tyre	225	50	R	17	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT MUDGUARD/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	BONNET/CENTER/LEFT	OTHER DAMAGES		ISOLATIE BINNENIN	
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	BONNET/CENTER/RIGHT	DENT		CHEMISCHE INWERKING	
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR
[x]	FRONT BUMPER/CENTER/RIGHT	OTHER DAMAGES		BESCHERMING ONTBREEKT	
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
2	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Pieces

	Number	Code	Description	Unit price	Depr.	Total
1	1	ISOLATIE		50.00 EUR	50 %	50.00 EUR
	Number	Code	Description	Unit price	Depr.	Total
2	1	RUBBER		50.00 EUR	50 %	50.00 EUR

1	2	3	4	5	6	7	8	9	10
74.00	74.00	290.08	318.35	0	0	0	0	0	0
37.00	37.00	145.04	159.18	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	756.43	0	756.43
HOG: 0	BG: 0		NA Deprec. 378.22
			0.00%
			TOTAL 378.22

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 29/03/2017 Hour : 10:37 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	