

Mileag ref. service :

www.vabfleetservices.be Date: 06/04/2017 1/4

ASR74N

#### [X] COLLECTION [X] EFFECTIVE [ ] NOT EXECUTED [ ] DELIVERY

[x] = Status Modification

Reg number / Chassis / Ref:

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: CLEAN [x] Mileage : Owner: 77919 KM

File nr. : Mileage start / arrival: 1387272 0 / 0

0 yr of constructionr : 1ESB991 / SJNFEAJ10U2704683 /

E-File nr. : First registration: 06/03/2013

VFS-nr.: Color: WHITE

Make + Model : Fuel type: NISSAN / QASHQAI **DIESEL** 

Object nr. : Fuel: 69812

**TISSUE** 

**Environment Class:** Classification: EURO 5

Co2: **Customer company: ROYAL & SUN ALLIANCE** 119g/km

**INSURANCE PLCI** Driver: Remote controls: 2

Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan):

Vehicle type: QASHQAI 2WD Tekna+N.Conn. St/St 130PK Country registration: **BELGIUM** 

VAT over the margin - car: No Metallic paint:

SUV Variant car: **Engine size:** 1598 Gear box: Number of places: 5 Manueel

Number of gears: 6 Number of doors: 5

HP: kW: 131 96

Fisc HP Imported vehicle:

Animals transported: Smoked in vehicle:

Extra set of tires: Due date vehicle inspection: No

> Use: Unknown

General condition:



www.vabfleetservices.be Date: 06/04/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

## Wheels and tyres: Summer tires

		[x] W	idth			He	ioht		Type		Rim	Index	l
Wheel RES:	[x]	ANDERE	Tyre:		OK		/	Rim:		/	Hubcap:		
Wheel RR:	[x]	BRIDGESTONE	Tyre:		OK	[x]	4-6 /	Rim:		/	Hubcap:		
Wheel FR:	[x]	GOODYEAR	Tyre:	[x]	OK	[x]	>6/	Rim:		/	Hubcap:		
Wheel RL:	[x]	BRIDGESTONE	Tyre:		OK	[x]	4-6 /	Rim:		/	Hubcap:		
Wheel FL:	[x]	GOODYEAR	Tyre :		OK	[x]	>6 /	Rim:		/	Hubcap:		

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	17	WINTER H
Rear tyre	215	60	R	17	WINTER H

Remark:

### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

 [x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 06/04/2017 3/4

### STATUS: ACCEPTABLE / USAGE DAMAGE

В	oo	lyν	vor	k	\&	win	d	lows	5
---	----	-----	-----	---	----	-----	---	------	---

[x] REAR DOOR/LEFT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

[x] FRONT DOOR/LEFT/REAR SCRATCH (WITHOUT PAINT DAMAGE) POLIEREN

[x] FRONT DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

#### STATUS: NOT ACCEPTABLE

#### Bodywork \& windows

[x] FRONT BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

 Repair paint - LI
 New paint - E
 Depr.
 Total

 1 0 LU = 0.00 EUR
 211.80 EUR
 50 %
 211.80 EUR

#### Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE SCRATCH WITH PAINT DAMAGE

1	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

1	2	3	4	5	6	7	8	9	10
211.80	115.56	0	0	0	0	0	0	0	0
105.90	115.56	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
327.36	0	211.80	115.56
NA Deprec. 221.46		BG: 0	HOG: 0
0.00%			

TOTAL 221.46



06/04/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No	)									
CIRCUMS	TANCES		NORMAL CONCLUSION							
Extra Time :	0 min	Waiting time: 0 mi Reason:	in	Towing time : Reason :	0 min					
NOT EXECUTED Reason:	: No	L		l						
Remark :										
Prices in EUR v	without VAT									
Authorized by customer :			Executed by VAB Fleet Se	ervices						
Remark authorized	customer :									
Date :	06/04/2017	<b>Hour:</b> 15:47								
Company :										
Executed by VAB F Services	leet									
E-Mail :	@									
Signature authorized	by customer									