

ANTM3R

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	157694 KM
File nr. :	1383385	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CEJ177 / WF0EXXGBBEBU06212 /		yr of constructionr :	/
E-File nr. :		First registration :	03/11/2011
VFS-nr. :		Color :	BLACK
Make + Model :	FORD / MONDEO	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SHEHERAZADE DEVELOPMENT	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	0 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	MONDEO BER Econetic Titanium 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
	Warning triangle : OK [x]
First aid kit : OK [x]	Oil level : OK [x]
Jack, wheelspanner :	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] SEMPERIT Tyre : OK [x] 2-4 / Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RL : [x] SEMPERIT Tyre : OK [x] 2-4 / Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel FR : [x] SEMPERIT Tyre : [x] OK [x] 2-4 / Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RR : [x] SEMPERIT Tyre : OK [x] 2-4 / Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	H
Rear tyre	215	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/LEFT/CENTER	DENT	
[x]	FRONT DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	
[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE	HERSTELD
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	

Interior

[x]	SEAT FR	SCRATCHED
-----	---------	-----------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/SIDE/RIGHT/CENTER	HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total
3	15 LU =72.00 EUR	0 EUR	235.80 EUR	50 %	307.80 EUR
[x]	REAR DOOR/LEFT/REAR	DENT			
	Number Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

RIM FRONT LEFT

	Number Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

	Number Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	REAR BUMPER	343.20 EUR	50 %	343.20 EUR

1	2	3	4	5	6	7	8	9	10
211.80	63.00	969.35	380.00	0	0	0	0	0	0
105.90	63.00	484.68	380.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
443.00	1181.15	0	1624.15
HOG: 0	BG: 0		NA Deprec. 1033.58
			0.00%
			TOTAL 1033.58

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/04/2017 Hour : 12:18 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	