

www.vabfleetservices.be Date: 10/04/2017 1/5

AT3PSU

#### [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	119902 KM
File nr. :	1387512	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EWC183 / WDD1760121J08	9169 /	yr of constructionr :	/
E-File nr. :		First registration :	04/04/2013
VFS-nr. :		Color :	BLACK
Make + Model :	MERCEDES / A	Fuel type :	DIESEL
Object nr. :	12349	Fuel :	
Classification:		Environment Class:	EURO 5
Customer company :	COMPUTER PROFILE BVBA	Co2:	98g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A 180 CDI BE 109PK	Country registration :	BELGIUM

Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	
Number of gears:	6	Number of doors:	5
HP:	109	kW:	80
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	

Metallic paint:

Yes



www.vabfleetservices.be Date: 10/04/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

#### Wheels and tyres: Summer tires

		[x] Wi	idth			He	ight		Туре		Rim	Index
Wheel RES:	[x]		Tyre:		OK		/	Rim:		/	Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap: [x	] SCRATCHED
Wheel FR:	[x]	BRIDGESTONE	Tyre:	[x]	OK	[x]	>6/	Rim:		/	<b>Hubcap:</b> [x	] SCRATCHED
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	<b>Hubcap:</b> [x	] SCRATCHED
Wheel FL:	[x]	BRIDGESTONE	Tyre:		OK	[x]	>6 /	Rim:		/	Hubcap: [x	] SCRATCHED

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	T
Rear tyre	195	65	R	15	T

Remark:

#### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 10/04/2017 3/5

#### STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows							
REAR DOOR/RIGHT/CENTER		SCRATCH WITH PAINT DA	.MAGE				
.] FRONT DOOR/LEFT/REAR		SCRATCH (WITHOUT PAIN	IT DAMAGE)	)			
FRONT DOOR/RIGHT/CENTER		SCRATCH WITH PAINT DA	SCRATCH WITH PAINT DAMAGE				
STATUS: NOT ACCEPTA	BLE						
Bodywork \& windows							
REAR BUMPER/CENTER/LEFT		DENT					
	Repair paint - LI	New paint - E		Depr.	Total		
3 0 LU =0.00 EUR	211.80 EUR			50 %	211.80 EUR		
FRONT BUMPER/RIGHT/SIDE	NT BUMPER/RIGHT/SIDE		MAGE				
	Repair paint - LI	New paint - E		Depr.	Total		
2 0 LU =0.00 EUR	211.80 EUR	'		50 %	211.80 EUR		
nterior							
] SEAT FL		STAIN					
Number Code	Description	U	nit price	Depr.	Total		
1 I 1 i-vab-rein-07	CLEANING (PER 15')	14	4.58 EUR		14.58 EUR		
] SEAT FR		STAIN					
Number Code	Description	U	nit price	Depr.	Total		
1 I 1 i-vab-rein-07	CLEANING (PER 15')	14	4.58 EUR	ı	14.58 EUR		
Others							
HUB CAP FL							
	Repair paint - LI	New paint - E		Depr.	Total		
4 0 LU =0.00 EUR				50 %			
HUB CAP REAR L							
	Repair paint - LI	New paint - E		Depr.	Total		
4 0 LU =0.00 EUR				50 %			
HUB CAP REAR RIGHT							
	Repair paint - LI	New paint - E		Depr.	Total		
4 0 LU =0.00 EUR		-		50 %			



www.vabfleetservices.be Date: 10/04/2017 4/5

Number	Code		Description			Unit price	Depr.		Total
<b>4</b> 1	WHEEL CAP					30.00 EUR	50 %		30.00 EUR
Number	Code		Description			Unit price	Depr.		Total
4 1	WHEEL CAP					30.00 EUR	50 %		30.00 EUR
Number	Code		Description			Unit price	Depr.		Total
4 1	WHEEL CAP					30.00 EUR	50 %		30.00 EUR
					_				
1	2	3	4	5	6	7	8	9	10
<b>1</b> 29.16	<b>2</b> 211.80	<b>3</b> 211.80	<b>4</b> 90.00	<b>5</b>	<b>6</b>	7	8	9	10
29.16 29.16	211.80	211.80 105.90	90.00	0	0	0	0	0	0
29.16 29.16 INNOV	211.80 105.90	211.80 105.90 TRADI	90.00	0	0	0	0	0	0
29.16 29.16 INNOV	211.80 105.90 VATIVE	211.80 105.90 TRADI	90.00 45.00 TIONAL	0	0 0 ENERAL	0	0	0	0

TOTAL

285.96



www.vabfleetservices.be Date: 10/04/2017 5/5

[x] = Status Modification

Pictures: N							
CIRCUMS	STANCES		UNDER CONDITION - VEHICLE VERY DIRTY				
Extra Time :	0 min	Waiting time : Reason :	0 min		Towing time : Reason :	0 min	
NOT EXECUTED Reason :	): No						
Remark:							
Prices in EUR	without VAT						
Authorized by				Executed by VAB	Fleet Services		
customer :				Elicented by 1122	2 1000 200 11000		
Remark authorized	d customer :						
Date :	10/04/2017	Hour:	13:02				
Company:							
Executed by VAB Services	Fleet						
E-Mail :	@						
Signature authorized	d by customer						
_							