

ARI63Y

☒ EFFECTIVE    ☐ NOT EXECUTED    ☒ COLLECTION    ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	72618 KM
File nr. :	1386341	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GXH125 / WF0MXXGBWMDK81574 /		yr of constructionr :	2014 / 00
E-File nr. :		First registration :	26/05/2014
VFS-nr. :		Color :	GREY
Make + Model :	FORD / GALAXY	Fuel type :	DIESEL
Object nr. :	64076	Fuel :	
Classification :	I	Environment Class:	EURO 5
Customer company :	GUDRUN COMMERCIAL NV	Co2:	139g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	7 [x]
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1997
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:	
--------------------	--

<b>Original registr. number :</b>	OK			<b>Service manual :</b>	OK	[x]
<b>Cert. of reg. / Part 1:</b>	OK	[x]		<b>Cert. of conformity :</b>	OK	
<b>Cert. of reg. copy / Part 2:</b>				<b>Insurance certificate :</b>		
<b>Warning vest :</b>				<b>Transport licence :</b>		
<b>Tax certificate :</b>				<b>Navigation CD/SD/DVD</b>		
<b>Fuel card :</b>				<b>Car radio :</b>	OK	[x]
<b>Mobile phone kit :</b>				<b>Extinguisher :</b>	OK	[x]
				<b>Warning triangle :</b>	OK	[x]
<b>First aid kit :</b>	OK	[x]		<b>Oil level :</b>	OK	[x]
<b>Jack, wheelspanner :</b>				<b>Filled up :</b>	0	

## Wheels and tyres: Winter tires

<b>Wheel FL:</b>	[x]	MICHELIN	<b>Tyre :</b>	OK	[x]	2-4 /	<b>Rim :</b>		/	<b>Hubcap :</b>	
<b>Wheel RL :</b>	[x]	MICHELIN	<b>Tyre :</b>	OK	[x]	2-4 /	<b>Rim :</b>		/	<b>Hubcap :</b>	
<b>Wheel FR :</b>	[x]	MICHELIN	<b>Tyre :</b>	[x]	OK	[x]	2-4 /	<b>Rim :</b>	[x]	WHEEL SCRATCHED	/ <b>Hubcap :</b>
<b>Wheel RR :</b>	[x]	MICHELIN	<b>Tyre :</b>	OK	[x]	2-4 /	<b>Rim :</b>	[x]	WHEEL SCRATCHED	/	<b>Hubcap :</b>
<b>Wheel RES:</b>	[x]		<b>Tyre :</b>	OK		/	<b>Rim :</b>		/	<b>Hubcap :</b>	

  

	[x]	<b>Width</b>	<b>Height</b>	<b>Type</b>	<b>Rim</b>	<b>Index</b>
<b>Front tyre</b>		225	50	R	17	M+S
<b>Rear tyre</b>		225	50	R	17	M+S

  

**Remark :**

### Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

  

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR DOOR/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR BUMPER/SIDE/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	ROOF STYLE/REAR/LEFT	SCRATCH WITH PAINT DAMAGE	DEELS NIET DOOR LAK

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	FRONT MUDGUARD/LEFT/CENTER	DENT			
Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	BONNET/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	348.09 EUR		50 %	348.09 EUR
[x]	REAR DOOR/LEFT/LEFT	OTHER DAMAGES		SLECHTE HERSTELLING	
Number	Code	Description	Unit price	Depr.	Total
0	0				

### Others

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
348.09	63.00	95.00	0	0	0	0	0	0	0
174.04	63.00	95.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
158.00	348.09	0	506.09
HOG: 0	BG: 2		NA Deprec. 332.04
			0.00%
			TOTAL 332.04

# APPRAISAL

**www.vabfleetservices.be**

**Date : 10/04/2017**

4/4

**[x] = Status Modification**

**Pictures :** No

## CIRCUMSTANCES

## NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min	Towing time : 0 min
	Reason :	Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

**Prices in EUR without VAT**

<b>Authorized by customer :</b>	Executed by VAB Fleet Services
<b>Remark authorized customer :</b>	
<b>Date :</b> 10/04/2017 <b>Hour :</b> 13:34	
<b>Company :</b>	
<b>Executed by VAB Fleet Services</b>	
<b>E-Mail :</b> @	
<b>Signature authorized by customer</b>	
	