

AR7RKJ

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	103545 KM
File nr. :	1386127	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ETU771 / VF34E9HP0DS040081 /		yr of constructionr :	/
E-File nr. :		First registration :	19/03/2013
VFS-nr. :		Color :	GREY
Make + Model :	PEUGEOT / 308	Fuel type :	DIESEL
Object nr. :	60859	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	COCKAERTS & CO II	Co2:	119g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	308 SW Access 92PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	92	kW:	68
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	Service manual :	OK	[x]
Cert. of reg. / Part 1:	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2: OK	Insurance certificate :		
Warning vest : [x]	Transport licence :		
Tax certificate :	Navigation CD/SD/DVD		
Fuel card :	Car radio :	OK	[x]
Mobile phone kit :	Extinguisher :	OK	[x]
	Warning triangle :	OK	[x]
First aid kit : OK [x]	Oil level :	OK	[x]
Jack, wheelspanner : OK [x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	/	Rim :	[x]	/	Hubcap :	[x]	SCRATCHED
Wheel RL :	[x]	FIRESTONE	Tyre :	OK	/	Rim :	[x]	/	Hubcap :	[x]	SCRATCHED
Wheel FR :	[x]	MICHELIN	Tyre :	OK	/	Rim :	[x]	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	FIRESTONE	Tyre :	OK	/	Rim :	[x]	/	Hubcap :	[x]	SCRATCHED
Wheel RES:	[x]		Tyre :	OK	/	Rim :		/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/CENTER

SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] FRONT BUMPER/LEFT/SIDE

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

HUB CAP FL

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

HUB CAP REAR L

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	90.00	0	0	0	0	0	0	0	0
105.90	45.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	301.80	0	301.80
HOG: 0	BG: 0		NA Deprec. 150.90
			0.00%
			TOTAL 150.90

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : KN0P RADIO PELT AF [x]		

Prices in EUR without VAT

<p>Authorized by customer :</p> <p>Remark authorized customer :</p> <p>Date : 10/04/2017 Hour : 12:03</p> <p>Company :</p> <p>Executed by VAB Fleet Services</p> <p>E-Mail : @</p>	<p>Executed by VAB Fleet Services</p>
<p>Signature authorized by customer</p> 	