

ARUW6L

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	148282 KM
File nr. :	1386615	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ERB945 / VF1KZ1A0748450999 /		yr of constructionr :	/
E-File nr. :		First registration :	27/02/2013
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / MEGANE BREAK	Fuel type :	DIESEL
Object nr. :	47327	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SGS BELGIUM NV	Co2:	104g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	MEGANE GT TomTom Edition 90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6 /	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	T
Rear tyre	195	65	R	15	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork l& windows

[x] REAR DOOR/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork l& windows

[x] REAR DOOR/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	301.68 EUR		50 %	301.68 EUR

[x] REAR MUDGUARD/LEFT/FRONT SCRATCH WITH PAINT DAMAGE +DEUK

	Repair paint - LI	New paint - E	Depr.	Total
7 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

[x] REAR BUMPER/SIDE/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x] REAR MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE +DEUK

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

[x] ROOF STYLE/CENTER/LEFT DENT

	Repair paint - LI	New paint - E	Depr.	Total
8 0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

[x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] WINDSCREEN/CENTER/LEFT HOLE/CRACK/TORN

	Repair paint - LI	New paint - E	Depr.	Total
10 0 LU =0.00 EUR	0 EUR		50 %	
	Repair paint - LI	New paint - E	Depr.	Total
10 25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

[x]	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR
[x]	ROOF/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	58.32 EUR

HUB CAP FL

		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	

HUB CAP REAR L

		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	

HUB CAP REAR RIGHT

		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	

HUB CAP FR

		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

Number	Code	Description	Unit price	Depr.	Total
--------	------	-------------	------------	-------	-------

1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
---	---	-----------	-----------	------	-----------

Number	Code	Description	Unit price	Depr.	Total
--------	------	-------------	------------	-------	-------

1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
---	---	-----------	-----------	------	-----------

Number	Code	Description	Unit price	Depr.	Total
--------	------	-------------	------------	-------	-------

1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
---	---	-----------	-----------	------	-----------

Number	Code	Description	Unit price	Depr.	Total
--------	------	-------------	------------	-------	-------

10	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR
----	---	-------------	------------	------	------------

1	2	3	4	5	6	7	8	9	10
178.32	220.18	520.00	301.68	318.35	0	308.20	220.18	481.50	487.20
118.32	110.09	260.00	150.84	159.18	0	154.10	110.09	240.75	243.60

INNOVATIVE	TRADITIONAL	GENERAL	
58.32	2977.29	0	3035.61
HOG: 0	BG: 0		NA Deprec. 1546.96
			0.00%
			TOTAL 1546.96

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/04/2017 Hour : 10:20 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	