

AQ0Q9T

☒ EFFECTIVE    ☐ NOT EXECUTED    ☒ COLLECTION    ☐ DELIVERY

[x] = Status Modification

|                               |                 |                          |                               |
|-------------------------------|-----------------|--------------------------|-------------------------------|
| Commissionar :                | KBC REMARKETING | Cleanliness :            | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner :                       |                 | Mileage :                | 180887 KM                     |
| File nr. :                    | 1385158         | Mileage start / arrival: | 0 / 0                         |
| Reg number / Chassis / Ref :  |                 | Mileag ref. service :    | 0                             |
| 1HTE592 / VF3LB9HPAES211542 / |                 | yr of constructionr :    | /                             |
| E-File nr. :                  |                 | First registration :     | 26/09/2014                    |
| VFS-nr. :                     |                 | Color :                  | GREY                          |
| Make + Model :                | PEUGEOT / 308   | Fuel type :              | DIESEL                        |
| Object nr. :                  | 54993           | Fuel :                   |                               |
| Classification :              |                 | Environment Class:       | EURO 5                        |
| Customer company :            | FOREM           | Co2:                     | 95g/km                        |
| Driver :                      |                 | Remote controls:         | 1                             |
| Covering :                    | TISSUE          | Number keys :            | 2 [x]                         |
| Vehicle kind :                | VEHICLE         | Seats (minivan) :        | 0                             |
| Vehicle type :                |                 | Country registration :   | BELGIUM                       |

|                              |                                |                     |         |
|------------------------------|--------------------------------|---------------------|---------|
| VAT over the margin - car:   |                                | Metallic paint:     | Yes     |
| Variant car:                 |                                | Engine size:        | 1560    |
| Gear box :                   | 5-speed automatic transmission | Number of places:   | 5       |
| Number of gears:             | 5                              | Number of doors:    | 5       |
| HP:                          | 92                             | kW:                 | 68      |
| Fisc HP                      |                                | Imported vehicle:   |         |
| Animals transported:         | No                             | Smoked in vehicle:  | No      |
| Due date vehicle inspection: |                                | Extra set of tires: | No      |
|                              |                                | Use:                | Unknown |
| General condition:           |                                |                     |         |

|                                     |    |     |                                |    |     |
|-------------------------------------|----|-----|--------------------------------|----|-----|
| <b>Original registr. number :</b>   | OK |     | <b>Service manual :</b>        | OK | [x] |
| <b>Cert. of reg. / Part 1:</b>      | OK | [x] | <b>Cert. of conformity :</b>   | OK |     |
| <b>Cert. of reg. copy / Part 2:</b> |    |     | <b>Insurance certificate :</b> |    |     |
| <b>Warning vest :</b>               | OK | [x] | <b>Transport licence :</b>     |    |     |
| <b>Tax certificate :</b>            |    |     | <b>Navigation CD/SD/DVD</b>    |    |     |
| <b>Fuel card :</b>                  |    |     | <b>Car radio :</b>             | OK | [x] |
| <b>Mobile phone kit :</b>           |    |     | <b>Extinguisher :</b>          | OK | [x] |
|                                     |    |     | <b>Warning triangle :</b>      | OK | [x] |
| <b>First aid kit :</b>              | OK | [x] | <b>Oil level :</b>             | OK | [x] |
| <b>Jack, wheelspanner :</b>         |    |     | <b>Filled up :</b>             | 0  |     |

## Wheels and tyres: Winter tires

|                   |     |            |               |     |     |       |              |              |   |                 |                 |           |           |
|-------------------|-----|------------|---------------|-----|-----|-------|--------------|--------------|---|-----------------|-----------------|-----------|-----------|
| <b>Wheel FL:</b>  | [x] | VREDESTEIN | <b>Tyre :</b> | OK  | [x] | 2-4 / | <b>Rim :</b> | [x]          | / | <b>Hubcap :</b> | [x]             | SCRATCHED |           |
| <b>Wheel RL :</b> | [x] | UNIROYAL   | <b>Tyre :</b> | OK  | [x] | 4-6 / | <b>Rim :</b> |              | / | <b>Hubcap :</b> |                 |           |           |
| <b>Wheel FR :</b> | [x] | VREDESTEIN | <b>Tyre :</b> | [x] | OK  | [x]   | 2-4 /        | <b>Rim :</b> |   | /               | <b>Hubcap :</b> | [x]       | SCRATCHED |
| <b>Wheel RR :</b> | [x] | UNIROYAL   | <b>Tyre :</b> | OK  | [x] | 4-6 / | <b>Rim :</b> |              | / | <b>Hubcap :</b> |                 |           |           |
| <b>Wheel RES:</b> | [x] | ANDERE     | <b>Tyre :</b> | OK  | [x] | >6 /  | <b>Rim :</b> |              | / | <b>Hubcap :</b> |                 |           |           |

|                   |     |              |               |             |            |              |
|-------------------|-----|--------------|---------------|-------------|------------|--------------|
|                   | [x] | <b>Width</b> | <b>Height</b> | <b>Type</b> | <b>Rim</b> | <b>Index</b> |
| <b>Front tyre</b> |     | 195          | 65            | R           | 15         | H            |
| <b>Rear tyre</b>  |     | 195          | 65            | R           | 15         | H            |

**Remark :**

## Wheels and tyres:

|            |        |    |   |       |   |          |
|------------|--------|----|---|-------|---|----------|
| Wheel FL:  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | Tyre : | OK | / | Rim : | / | Hubcap : |

|            |       |        |      |     |       |
|------------|-------|--------|------|-----|-------|
| [x]        | Width | Height | Type | Rim | Index |
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

|     |                        |                                |     |
|-----|------------------------|--------------------------------|-----|
| [x] | REAR DOOR/RIGHT/CENTER | SCRATCH (WITHOUT PAINT DAMAGE) |     |
| [x] | REAR DOOR/RIGHT/FRONT  | DENT                           | 5 X |
| [x] | FRONT DOOR/LEFT/CENTER | DENT                           |     |
| [x] | BONNET/CENTER/LEFT     | SCRATCH WITH PAINT DAMAGE      |     |

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

|     |                              |               |                     |                           |       |            |
|-----|------------------------------|---------------|---------------------|---------------------------|-------|------------|
| [x] | REAR BUMPER/CENTER/LEFT      |               |                     | HOLE/CRACK/TORN           |       |            |
|     |                              |               | Repair paint - LI   | New paint - E             | Depr. | Total      |
| 2   | 15 LU =72.00 EUR             |               | 0 EUR               | 235.80 EUR                | 50 %  | 307.80 EUR |
| [x] | REAR MUDGUARD/RIGHT/CENTER   |               |                     | SCRATCH WITH PAINT DAMAGE |       |            |
|     |                              |               | Repair paint - LI   | New paint - E             | Depr. | Total      |
| 3   | 0 LU =0.00 EUR               |               | 308.20 EUR          |                           | 50 %  | 308.20 EUR |
| [x] | FRONT DOOR/RIGHT/CENTER      |               |                     | DENT                      |       | 7X         |
|     | Number                       | Code          | Description         | Unit price                | Depr. | Total      |
| 4   | I 1                          | i-vab-uitd-01 | BEAT OUT DENT       | 63.00 EUR                 |       | 63.00 EUR  |
|     | Number                       | Code          | Description         | Unit price                | Depr. | Total      |
| 4   | I 6                          | i-vab-uitd-02 | BEAT OUT DENT SUPPL | 19.80 EUR                 |       | 118.80 EUR |
| [x] | FRONT THRESHOLD/RIGHT/CENTER |               |                     | DENT                      |       |            |
|     |                              |               | Repair paint - LI   | New paint - E             | Depr. | Total      |
| 5   | 0 LU =0.00 EUR               |               | 310.50 EUR          |                           | 50 %  | 310.50 EUR |
| [x] | FRONT BUMPER/RIGHT/SIDE      |               |                     | SCRATCH WITH PAINT DAMAGE |       |            |
|     |                              |               | Repair paint - LI   | New paint - E             | Depr. | Total      |
| 1   | 0 LU =0.00 EUR               |               | 211.80 EUR          |                           | 50 %  | 211.80 EUR |

### Accessories and others

|     |                               |                |                 |                           |       |            |
|-----|-------------------------------|----------------|-----------------|---------------------------|-------|------------|
| [x] | OUTSIDE MIRROR RIGHTHAND SIDE |                |                 | SCRATCH WITH PAINT DAMAGE |       |            |
|     | Number                        | Code           | Description     | Unit price                | Depr. | Total      |
| 6   | I 1                           | i-vab-kunst-01 | PLASTICS REPAIR | 110.64 EUR                |       | 110.64 EUR |

## Others

HUB CAP FL

|                  | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|-------|
| 7 0 LU =0.00 EUR |                   |               | 50 %  |       |

HUB CAP FR

|                  | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|-------|
| 7 0 LU =0.00 EUR |                   |               | 50 %  |       |

## Pieces

| Number | Code | Description | Unit price | Depr. | Total      |
|--------|------|-------------|------------|-------|------------|
| 2      | 1    | REAR BUMPER | 343.20 EUR | 50 %  | 343.20 EUR |
| Number | Code | Description | Unit price | Depr. | Total      |
| 7      | 1    | WHEEL CAP   | 30.00 EUR  | 50 %  | 30.00 EUR  |
| Number | Code | Description | Unit price | Depr. | Total      |
| 7      | 1    | WHEEL CAP   | 30.00 EUR  | 50 %  | 30.00 EUR  |

| 1      | 2      | 3      | 4      | 5      | 6      | 7     | 8 | 9 | 10 |
|--------|--------|--------|--------|--------|--------|-------|---|---|----|
| 211.80 | 651.00 | 308.20 | 181.80 | 310.50 | 110.64 | 60.00 | 0 | 0 | 0  |
| 105.90 | 325.50 | 154.10 | 181.80 | 155.25 | 110.64 | 30.00 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                    |
|------------|-------------|---------|--------------------|
| 292.44     | 1541.50     | 0       | 1833.94            |
| HOG: 0     | BG: 0       |         | NA Deprec. 1063.19 |
|            |             |         | 0.00%              |
|            |             |         | TOTAL 1063.19      |

# APPRAISAL

**www.vabfleetservices.be**

**Date :** 06/04/2017

5/5

**[x] = Status Modification**


**Pictures :** No

## CIRCUMSTANCES

## NORMAL CONCLUSION

|                                             |                                                |                                               |
|---------------------------------------------|------------------------------------------------|-----------------------------------------------|
| <b>Extra Time :</b> 0 min<br>               | <b>Waiting time :</b> 0 min<br><b>Reason :</b> | <b>Towing time :</b> 0 min<br><b>Reason :</b> |
| <b>NOT EXECUTED :</b> No<br><b>Reason :</b> |                                                |                                               |
| <b>Remark :</b>                             |                                                |                                               |

**Prices in EUR without VAT**

|                                                                                                                                |                                |
|--------------------------------------------------------------------------------------------------------------------------------|--------------------------------|
| <b>Authorized by customer :</b>                                                                                                | Executed by VAB Fleet Services |
| <b>Remark authorized customer :</b>                                                                                            |                                |
| <b>Date :</b> 06/04/2017 <b>Hour :</b> 14:51                                                                                   |                                |
| <b>Company :</b><br><b>Executed by VAB Fleet Services</b><br><b>E-Mail :</b> @                                                 |                                |
| <b>Signature authorized by customer</b><br> |                                |