

AQUVO9

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	146126 KM
File nr. :	1385842	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GAA485 / VF1BR2V0H49878439 /		yr of constructionr :	/
E-File nr. :		First registration :	03/12/2013
VFS-nr. :		Color :	RED
Make + Model :	RENAULT / CLIO	Fuel type :	DIESEL
Object nr. :	75416	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	MCH LEUVEN CVBA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	CLIO COLLECTION BER 75PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:		Engine size:	
Gear box :		Number of places:	
Number of gears:		Number of doors:	
HP:		kW:	
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	
General condition:			

Original registr. number :	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity :
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio :
Mobile phone kit :	Extinguisher :
First aid kit :	Warning triangle :
Jack, wheelspanner :	Oil level :
	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL:	[x]	KLÉBER	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	KLÉBER	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	KLÉBER	Tyre :	[x]	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	KLÉBER	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	185	60	R	15	T
Rear tyre	185	60	R	15	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/LEFT/CENTER	DENT
[x]	REAR DOOR/LEFT/CENTER	DENT
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	-------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER		HOLE/CRACK/TORN			
			Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR		0 EUR		50 %	
			Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR		0 EUR	188.64 EUR	50 %	188.64 EUR
[x]	REAR BUMPER/SIDE/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
0	0					
[x]	REAR MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR		246.56 EUR		50 %	246.56 EUR
[x]	REAR DOOR/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR		254.68 EUR		50 %	254.68 EUR
[x]	FRONT BUMPER/RIGHT/CORNER		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR		169.44 EUR		50 %	169.44 EUR
[x]	ROOF/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR		385.20 EUR		50 %	385.20 EUR

Interior

[x] SEAT FL STAIN

Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR	14.58 EUR

Others

HUB CAP FL

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR			50 %	

HUB CAP REAR L

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR			50 %	

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

Number	Code	Description	Unit price	Depr.	Total
4	1	REAR BUMPER	274.56 EUR	50 %	274.56 EUR

1	2	3	4	5	6	7	8	9	10
96.00	169.44	501.24	463.20	385.20	14.58	0	0	0	0
48.00	84.72	250.62	231.60	192.60	14.58	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
14.58	1615.08	0	1629.66
HOG: 0	BG: 1		NA Deprec. 822.12
			0.00%
			TOTAL 822.12

APPRAISAL

www.vabfleetservices.be

Date : 07/04/2017

6/6

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

Extra Time : 0 min 	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 07/04/2017 Hour : 11:32	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	