

AR606M

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	124772 KM
File nr. :	1386093	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CWR039 / VF1FW14B546990430 /		yr of constructionr :	/
E-File nr. :		First registration :	14/03/2012
VFS-nr. :		Color :	WHITE
Make + Model :	RENAULT / KANGOO EXPRESS	Fuel type :	DIESEL
Object nr. :	32796	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ARAMARK SA	Co2:	137g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	KANGOO Expr. B/F PLC Gr.Conf.(EU5)75PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BESTELWAGEN	Engine size:	1461
Gear box :	Manueel	Number of places:	2
Number of gears:	5	Number of doors:	5
HP:	75	kW:	55
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	
Mobile phone kit :		Extinguisher :	OK [x]
		Warning triangle :	OK [x]
First aid kit :	OK [x]	Oil level :	OK [x]
Jack, wheelspanner :	OK [x]	Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	SEMPERIT	Tyre :	OK	[x]	1.6-2 /	Rim :		/	Hubcap :	
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	1.6-2 /	Rim :		/	Hubcap :	
Wheel FR :	[x]	SEMPERIT	Tyre :	[x]	OK	[x]	1.6-2 /	Rim :		/	Hubcap :
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	1.6-2 /	Rim :		/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	T
Rear tyre	195	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/LEFT/LEFT	DENT

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER			SCRATCH (WITHOUT PAINT DAMAGE)		
			Repair paint - LI	New paint - E	Depr.	Total
2	15 LU =72.00 EUR		0 EUR			72.00 EUR
[x]	FRONT DOOR/LEFT/REAR			DENT		
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

Interior

[x]	SEAT FL	HOLE			
		Repair paint - LI	New paint - E	Depr.	Total
3	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

Pieces

	Number	Code	Description	Unit price	Depr.	Total
2	1	REAR BUMPER		257.40 EUR		257.40 EUR
	Number	Code	Description	Unit price	Depr.	Total
2	1	MISTLICHT IN BUMPER		30.00 EUR		30.00 EUR
	Number	Code	Description	Unit price	Depr.	Total
3	1	SEAT UPHOLSTERY TISSUE		90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
115.56	359.40	210.00	0	0	0	0	0	0	0
115.56	359.40	105.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
115.56	569.40	0	684.96
HOG: 0	BG: 3		NA Deprec. 579.96
			0.00%
			TOTAL 579.96

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/04/2017 Hour : 09:28 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	