

ATROGL

☒ EFFECTIVE    ☐ NOT EXECUTED    ☒ COLLECTION    ☐ DELIVERY

[x] = Status Modification

|                               |                               |                          |                               |
|-------------------------------|-------------------------------|--------------------------|-------------------------------|
| Commissionar :                | KBC REMARKETING               | Cleanliness :            | INT: CLEAN [x] EXT: DIRTY [x] |
| Owner :                       |                               | Mileage :                | 120799 KM                     |
| File nr. :                    | 1388018                       | Mileage start / arrival: | 0 / 0                         |
| Reg number / Chassis / Ref :  |                               | Mileag ref. service :    | 0                             |
| 1EYL339 / VF1JZ140648764598 / |                               | yr of constructionr :    | 2013 / 00                     |
| E-File nr. :                  |                               | First registration :     | 22/04/2013                    |
| VFS-nr. :                     |                               | Color :                  | SILVER                        |
| Make + Model :                | RENAULT / SCENIC              | Fuel type :              | DIESEL                        |
| Object nr. :                  | 46483                         | Fuel :                   |                               |
| Classification :              |                               | Environment Class:       | EURO 5                        |
| Customer company :            | RANDSTAD GROUP BELGIUM NV     | Co2:                     | 105g/km                       |
| Driver :                      |                               | Remote controls:         | 2                             |
| Covering :                    | TISSUE                        | Number keys :            | 2 [x]                         |
| Vehicle kind :                |                               | Seats (minivan) :        | 0                             |
| Vehicle type :                | SCENIC Energ.Expression 110PK | Country registration :   | BELGIUM                       |

|                              |         |                     |         |
|------------------------------|---------|---------------------|---------|
| VAT over the margin - car:   | No      | Metallic paint:     | Yes     |
| Variant car:                 |         | Engine size:        | 1461    |
| Gear box :                   | Manueel | Number of places:   | 5       |
| Number of gears:             | 6       | Number of doors:    | 5       |
| HP:                          | 110     | kW:                 | 81      |
| Fisc HP                      |         | Imported vehicle:   |         |
| Animals transported:         |         | Smoked in vehicle:  |         |
| Due date vehicle inspection: |         | Extra set of tires: |         |
|                              |         | Use:                | Unknown |

|                    |
|--------------------|
| General condition: |
|--------------------|

|                                     |                           |
|-------------------------------------|---------------------------|
| Original registr. number : OK       | Service manual :          |
| Cert. of reg. / Part 1:             | Cert. of conformity : OK  |
| Cert. of reg. copy / Part 2: OK [x] | Insurance certificate :   |
| Warning vest :                      | Transport licence :       |
| Tax certificate :                   | Navigation CD/SD/DVD      |
| Fuel card :                         | Car radio : OK [x]        |
| Mobile phone kit :                  | Extinguisher : OK [x]     |
|                                     | Warning triangle : OK [x] |
| First aid kit : OK [x]              | Oil level : OK [x]        |
| Jack, wheelspanner : OK [x]         | Filled up : 0             |

## Wheels and tyres: Winter tires

|                       |                         |         |                        |
|-----------------------|-------------------------|---------|------------------------|
| Wheel FL: [x] KLÉBER  | Tyre : OK [x] 2-4 /     | Rim : / | Hubcap : [x] SCRATCHED |
| Wheel RL : [x] KLÉBER | Tyre : OK [x] 4-6 /     | Rim : / | Hubcap : [x] SCRATCHED |
| Wheel FR : [x] KLÉBER | Tyre : [x] OK [x] 2-4 / | Rim : / | Hubcap : [x] SCRATCHED |
| Wheel RR : [x] KLÉBER | Tyre : OK [x] 4-6 /     | Rim : / | Hubcap : [x] SCRATCHED |
| Wheel RES: [x]        | Tyre : OK /             | Rim : / | Hubcap :               |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205   | 60     | R    | 16  | M+S   |
| Rear tyre  | 205   | 60     | R    | 16  | M+S   |

Remark :

## Wheels and tyres:

|            |             |         |          |
|------------|-------------|---------|----------|
| Wheel FL:  | Tyre : OK / | Rim : / | Hubcap : |
| Wheel RL : | Tyre : OK / | Rim : / | Hubcap : |
| Wheel FR : | Tyre : OK / | Rim : / | Hubcap : |
| Wheel RR : | Tyre : OK / | Rim : / | Hubcap : |
| Wheel RES: | Tyre : OK / | Rim : / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

|     |                            |                           |                     |
|-----|----------------------------|---------------------------|---------------------|
| [x] | REAR MUDGUARD/LEFT/FRONT   | SCRATCH WITH PAINT DAMAGE | DEELS NIET DOOR LAK |
| [x] | REAR MUDGUARD/RIGHT/CENTER | DENT                      |                     |
| [x] | REAR DOOR/LEFT/CENTER      | SCRATCH WITH PAINT DAMAGE | DEELS NIET DOOR LAK |
| [x] | FRONT MUDGUARD/LEFT/FRONT  | SCRATCH WITH PAINT DAMAGE | DEELS NIET DOOR LAK |

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

|     |                           |                |                   |                           |       |            |
|-----|---------------------------|----------------|-------------------|---------------------------|-------|------------|
| [x] | REAR BUMPER/CENTER/RIGHT  |                |                   | SCRATCH WITH PAINT DAMAGE |       |            |
|     | Number                    | Code           | Description       | Unit price                | Depr. | Total      |
| 3   | I 1                       | i-vab-kunst-01 | PLASTICS REPAIR   | 110.64 EUR                |       | 110.64 EUR |
| [x] | REAR MUDGUARD/CENTER/LEFT |                |                   | SCRATCH WITH PAINT DAMAGE |       |            |
|     |                           |                | Repair paint - LI | New paint - E             | Depr. | Total      |
| 2   | 0 LU =0.00 EUR            |                | 258.28 EUR        |                           | 50 %  | 258.28 EUR |
| [x] | FRONT DOOR/LEFT/REAR      |                |                   | SCRATCH WITH PAINT DAMAGE |       | + DEUKEN   |
|     |                           |                | Repair paint - LI | New paint - E             | Depr. | Total      |
| 1   | 0 LU =0.00 EUR            |                | 318.35 EUR        |                           | 50 %  | 318.35 EUR |

### Others

|  | HUB CAP FL         |                |                   |               |       |       |
|--|--------------------|----------------|-------------------|---------------|-------|-------|
|  |                    |                | Repair paint - LI | New paint - E | Depr. | Total |
|  | 4                  | 0 LU =0.00 EUR |                   |               | 50 %  |       |
|  | HUB CAP REAR L     |                |                   |               |       |       |
|  |                    |                | Repair paint - LI | New paint - E | Depr. | Total |
|  | 4                  | 0 LU =0.00 EUR |                   |               | 50 %  |       |
|  | HUB CAP REAR RIGHT |                |                   |               |       |       |
|  |                    |                | Repair paint - LI | New paint - E | Depr. | Total |
|  | 4                  | 0 LU =0.00 EUR |                   |               | 50 %  |       |
|  | HUB CAP FR         |                |                   |               |       |       |
|  |                    |                | Repair paint - LI | New paint - E | Depr. | Total |
|  | 4                  | 0 LU =0.00 EUR |                   |               | 50 %  |       |

## Pieces

| Number | Code | Description | Unit price | Depr. | Total     |
|--------|------|-------------|------------|-------|-----------|
| 4      | 1    | WHEEL CAP   | 30.00 EUR  | 50 %  | 30.00 EUR |
| Number | Code | Description | Unit price | Depr. | Total     |
| 4      | 1    | WHEEL CAP   | 30.00 EUR  | 50 %  | 30.00 EUR |
| Number | Code | Description | Unit price | Depr. | Total     |
| 4      | 1    | WHEEL CAP   | 30.00 EUR  | 50 %  | 30.00 EUR |
| Number | Code | Description | Unit price | Depr. | Total     |
| 4      | 1    | WHEEL CAP   | 30.00 EUR  | 50 %  | 30.00 EUR |

| 1      | 2      | 3      | 4      | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|--------|---|---|---|---|---|----|
| 318.35 | 258.28 | 110.64 | 120.00 | 0 | 0 | 0 | 0 | 0 | 0  |
| 159.18 | 129.14 | 110.64 | 60.00  | 0 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                   |
|------------|-------------|---------|-------------------|
| 110.64     | 696.63      | 0       | 807.27            |
| HOG: 0     | BG: 0       |         | NA Deprec. 458.96 |
|            |             |         | 0.00%             |
|            |             |         | TOTAL 458.96      |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|                               |                                  |                                 |
|-------------------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min            | Waiting time : 0 min<br>Reason : | Towing time : 0 min<br>Reason : |
| NOT EXECUTED : No<br>Reason : |                                  |                                 |
| Remark :                      |                                  |                                 |

## Prices in EUR without VAT

|                                                                                                                                                                      |                                |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|
| Authorized by customer :<br><br>Remark authorized customer :<br><br>Date : 11/04/2017      Hour : 16:51<br>Company :<br>Executed by VAB Fleet Services<br>E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br>                                              |                                |