

AU84BX

☒ EFFECTIVE   
 ☐ NOT EXECUTED   
 ☒ COLLECTION   
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	139017 KM
File nr. :	1388365	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DED896 / YV1MW84F1C2696707 /		yr of constructionr :	/
E-File nr. :		First registration :	20/04/2012
VFS-nr. :		Color :	BLACK
Make + Model :	VOLVO / V50	Fuel type :	DIESEL
Object nr. :	69255	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	EURO SHOE GROUP NV	Co2:	99g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	V50 BRE DRIVe Start/Stop 99g 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:
--------------------

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

## Wheels and tyres: Winter tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :	
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	>6 /	Rim :		/	Hubcap :	
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	4-6 /	Rim :		/	Hubcap :
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	>6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	DENT
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT
[x]	REAR DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
-----	-------------------------	---------------------------

Number	Code	Description	Unit price	Depr.	Total
0	0				

[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	+DEUK
-----	--------------------------	---------------------------	-------

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

[x]	REAR DOOR/RIGHT/FRONT	DENT
-----	-----------------------	------

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	308.20	0	0	0	0	0	0	0	0
63.00	154.10	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	308.20	0	371.20
HOG: 0	BG: 0		NA Deprec. 217.10
			0.00%
			TOTAL 217.10

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

## Prices in EUR without VAT

Authorized by customer :  Remark authorized customer :  Date : 12/04/2017      Hour : 12:49 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	