

AQ1AD8

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	25060 KM
File nr. :	1385169	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1JKL277 / WVWZZZAUZFW185637 /		yr of constructionr :	/
E-File nr. :		First registration :	12/01/2015
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	59063	Fuel :	
Classification :	E	Environment Class:	EURO 5
Customer company :	VAB RIJSCHOOL NV	Co2:	98g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK
Jack, wheelspanner :		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4 /	Rim :	/ Hubcap : [x] MISSING/INCOMPLETE
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel RES:	[x]	CONTINENTAL	Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] FRONT DOOR/LEFT/REAR DENT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	63.00 EUR

Others

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
2	0	LU =0.00 EUR	50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	30.00	0	0	0	0	0	0	0	0
63.00	15.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	30.00	0	93.00
HOG: 0	BG: 0		NA Deprec. 78.00
			0.00%
			TOTAL 78.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 11/04/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	