

AQ1LBH

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	19995 KM
File nr. :	1385176	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1JTN310 / WVWZZZAUZFW223565 /		yr of constructionr :	/
E-File nr. :		First registration :	23/02/2015
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	59063	Fuel :	
Classification :	E	Environment Class:	EURO 5
Customer company :	VAB RIJSCHOOL NV	Co2:	98g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		[x]	Insurance certificate :	
Warning vest :			Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	OK	/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:	[x]	CONTINENTAL	Tyre :	OK	/	Rim :	/	Hubcap :	
	[x]								
		Width	Height	Type		Rim		Index	
Front tyre		195	65	R		15		H	
Rear tyre		195	65	R		15		H	

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	
		Width	Height	Type		Rim		Index
Front tyre		0	0	R		0		
Rear tyre		0	0	R		0		

Remark :

Conclusion

Bodywork \& windows

[x] FRONT DOOR/LEFT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR DOOR/RIGHT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

[x] FRONT DOOR/RIGHT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)

[x] FRONT MUDGUARD/RIGHT/CENTER DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] FRONT MUDGUARD/LEFT/FRONT SCRATCH WITH PAINT DAMAGE

		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 1	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	14.58 EUR

HUB CAP FR

		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
14.58	211.80	220.18	30.00	0	0	0	0	0	0
14.58	105.90	110.09	15.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
14.58	461.98	0	476.56
HOG: 0	BG: 0		NA Deprec. 245.57
			0.00%
			TOTAL 245.57

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 11/04/2017 Hour : 09:40 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	