

9KL074

☒ EFFECTIVE ☐ NOT EXECUTED ☐ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: EXT: VERY DIRTY [x]
Owner :		Mileage :	153625 KM
File nr. :	1352908	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
DV4798 / WVWZZZ1KZDW103835 /		yr of constructionr :	/
E-File nr. :		First registration :	05/11/2012
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :	E	Environment Class:	
Customer company :	WRAK KBC REMARKETING	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:		kW:	
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity :
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest : OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
	Warning triangle : OK [x]
First aid kit : OK [x]	Oil level : [x]
Jack, wheelspanner :	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	>6 /	Rim :	/	Hubcap :
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	2-4 /	Rim :	/
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	>6 /	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	WINTER T
Rear tyre	195	65	R	15	WINTER T

Remark : VELGEN VUIL

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT

SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Interior

[x] SEAT FL

DIRTY

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR	14.58 EUR

1	2	3	4	5	6	7	8	9	10
14.58	0	0	0	0	0	0	0	0	0
14.58	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
14.58	0	0	14.58
HOG: 0	BG: 0		NA Deprec. 14.58
			0.00%
			TOTAL 14.58

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE VERY DIRTY

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 03/01/2017 Hour : 14:39 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	