

www.vabfleetservices.be Date: 06/07/2017 1/5

BR81CW

### [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	141489 KM
File nr. :	1414022	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
IDLP911 / WAUZZZ8P7CA1	45499 /	yr of constructionr :	/
E-File nr. :		First registration :	18/06/2012
VFS-nr. :		Color :	SILVER
Make + Model :	AUDI / A3	Fuel type :	DIESEL
Object nr. :		Fuel:	
Classification:		Environment Class:	EURO 5
Customer company:	EDF LUMINUS	Co2:	115g/km
Oriver :		Remote controls:	2
Covering:	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	A3 SB Ambition Start/Stop DPF 136PK	Country registration :	BELGIUM

		_	
Variant car:		Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		I	

Metallic paint:

Yes



www.vabfleetservices.be Date: 06/07/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:		[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :		
Jack, wheelspanner :	OK	[x]	Filled up :	0	

### Wheels and tyres: Summer tires

		[x]	Width				eight			Type		Rim	Index
Wheel RES:	[x]	ANDERE	Tyre:		OK		/	Rim:				/ Hubcap:	
Wheel RR:	[x]	GOODYEAR	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	)	/ Hubcap:	
Wheel FR:	[x]	ANDERE	Tyre:	[x]	OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED	)	/ Hubcap:	
Wheel RL:	[x]	GOODYEAR	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	)	/ Hubcap:	
Wheel FL:	[x]	ANDERE	Tyre:		OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	)	/ Hubcap:	

[x]	Width	Height	Туре	Rim	Index
Front tyre	225	45	R	17	Y
Rear tyre	225	45	R	17	Y

Remark:

### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
1					

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 06/07/2017 3/5

#### STATUS: ACCEPTABLE / USAGE DAMAGE

	ATUS. ACCEPTABLE / C					
Во	dywork \& windows					
[x]	REAR MUDGUARD/LEFT/FRONT		SCRATCH WITH PAINT	DAMAGE		
[x]	REAR DOOR/LEFT/CENTER		SCRATCH (WITHOUT PA	AINT DAMAGE	)	
[x]	BONNET/CENTER/RIGHT/FRONT		CHIPS			
[x]	FRONT BUMPER/RIGHT		SCRATCH WITH PAINT	DAMAGE	ONDER	
nte	erior					
[x]	BOOT LID IN		SCRATCHED			
Ac	cessories and others					
[x]	OUTSIDE MIRROR LEFTHAND SIDE		SCRATCH WITH PAINT	DAMAGE		
[x]	OUTSIDE MIRROR RIGHTHAND SIDE		SCRATCH (WITHOUT PA	AINT DAMAGE	)	
ST	ATUS: NOT ACCEPTAB	LE				
Во	dywork \& windows					
x]	REAR BUMPER/LEFT/LEFT		SCRATCH WITH PAINT	DAMAGE	MEERDERE	
		Repair paint - LI	New paint - E		Depr.	Total
	1 0 LU =0.00 EUR	169.44 EUR			50 %	169.44 EUR
x]	REAR WINDOW/LEFT		SCRATCH WITH PAINT	DAMAGE		
		Repair paint - LI	New paint - E		Depr.	Total
	2 10 LU =48.00 EUR	0 EUR			50 %	48.00 EUR
Oth	ners					
	RIM REAR LEFT					
	Number Code	Description		Unit price	Depr.	Total
	3 I 1 i-vab-herstalu-02	REPAIR ALLOY WHI	EEL	95.00 EUR		95.00 EUR
	RIM FRONT RIGHT					
	Number Code	Description		Unit price	Depr.	Total
	3 I 1 i-vab-herstalu-02	REPAIR ALLOY WHI	EEL	95.00 EUR		95.00 EUR
Pie	ces					
	Number Code	Description		Unit price	Depr.	Total
	2 1 BACK WINDOW			200.00 EUR	50 %	200.00 EUR



www.vabfleetservices.be Date: 06/07/2017 4/5

1	2	3	4	5	6	7	8	9	10
169.44	248.00	190.00	0	0	0	0	0	0	0
84.72	124.00	190.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
190.00	417.44	0		607.44
HOG: 0	BG: 1		NA Deprec.	398.72
			0.00%	
			TOTAL	398.72



www.vabfleetservices.be Date: 06/07/2017 5/5

[x] = Status Modification

Pictures: No

**CIRCUMSTANCES** 

NORMAL CONCLUSION

		NORWIAL CONCLUSION						
Extra Time :	0 min	Waiting t	ime: 0 min		Towing time :	0 min		
		Reason :			Reason:			
NOT EXECUTED	: No							
Reason :								
Remark:	GEEN NAVI [x]							
Prices in EUR	without VAT							
Authorized by customer:				Executed by VAB Fleet Se	ervices			
Remark authorized	d customer :							
Date :	06/07/2017	Hour:	15:53					
Company :								
Executed by VAB Services	Fleet							
E-Mail:								
Signature authorized	d by customer							
×								