

BWSPDZ

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	151164 KM
File nr. :	1418354	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DFB046 / WF0HXXWPBHCA63859 /		yr of constructionr :	/
E-File nr. :		First registration :	26/04/2012
VFS-nr. :		Color :	BROWN
Make + Model :	FORD / C-MAX	Fuel type :	DIESEL
Object nr. :	49284	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	TEMPO-TEAM GROUP BELGIUM	Co2:	124g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	GR.C-MAX Trend St/St 95PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1560
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	95	kW:	70
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK			Service manual :	OK	[x]
Cert. of reg. / Part 1:				Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]		Insurance certificate :		
Warning vest :	OK	[x]		Transport licence :		
Tax certificate :				Navigation CD/SD/DVD	OK	[x]
Fuel card :				Car radio :	OK	[x]
Mobile phone kit :				Extinguisher :	OK	[x]
				Warning triangle :	OK	[x]
First aid kit :	OK	[x]		Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL :	[x]	KLÉBER	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :		
Wheel RL :	[x]	KLÉBER	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :		
Wheel FR :	[x]	KLÉBER	Tyre :	[x]	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel RR :	[x]	KLÉBER	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :		

	[x]	Width	Height	Type	Rim	Index
Front tyre		215	55	R	16	V
Rear tyre		215	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/CORNER		OTHER DAMAGES			
	Number	Code	Description	Unit price	Depr.	Total
	2	I 1	i-vab-ander-01	REPAIR (PER 15')	18.74 EUR	18.74 EUR
[x]	REAR WINDOW/LEFT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
	3	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	FRONT MUDGUARD/LEFT/FRONT		DENT			
	Number	Code	Description	Unit price	Depr.	Total
	1	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR	115.56 EUR
[x]	FRONT BUMPER/LEFT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
	1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Pieces

	Number	Code	Description	Unit price	Depr.	Total
	3	1	BACK WINDOW	250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
327.36	18.74	370.00	0	0	0	0	0	0	0
221.46	18.74	185.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
134.30	581.80	0	716.10
HOG: 0	BG: 0		NA Deprec. 425.20
			0.00%
			TOTAL 425.20

APPRAISAL

www.vabfleetservices.be

Date : 12/07/2017

4/4

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min	Towing time : 0 min
	Reason :	Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 12/07/2017 Hour : 13:06	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	