

BTV6EU

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------|---------------------------|--------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 145213 KM |
| File nr. : | 1416135 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1DHD476 / WF0HXXWPBHCA53716 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 15/05/2012 |
| VFS-nr. : | | Color : | BROWN |
| Make + Model : | FORD / C-MAX | Fuel type : | DIESEL |
| Object nr. : | 37852 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | JAVA BVBA | Co2: | 124g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | GR.C-MAX Trend St/St 95PK | Country registration : | BELGIUM |

| | | | |
|------------------------------|---------|---------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | | Engine size: | 1560 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 95 | kW: | 70 |
| Fisc HP | | Imported vehicle: | No |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

| | |
|--------------------|--|
| General condition: | |
|--------------------|--|

| | | | | |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | | Navigation CD/SD/DVD | |
| Fuel card : | | | Car radio : | OK [x] |
| Mobile phone kit : | | | Extinguisher : | OK [x] |
| | | | Warning triangle : | OK [x] |
| First aid kit : | OK | [x] | Oil level : | OK [x] |
| Jack, wheelspanner : | | | Filled up : | 0 |

Wheels and tyres: Winter tires

| | | | | | | | | | | | |
|------------|-----|----------|--------|-----|-----|-------|-------|-------|-----------------|---|----------|
| Wheel FL: | [x] | MICHELIN | Tyre : | OK | [x] | 4-6 / | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK | [x] | 4-6 / | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : |
| Wheel FR : | [x] | MICHELIN | Tyre : | [x] | OK | [x] | 4-6 / | Rim : | | / | Hubcap : |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK | [x] | 4-6 / | Rim : | | | / | Hubcap : |
| Wheel RES: | [x] | | Tyre : | OK | | / | Rim : | | | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 215 | 55 | R | 16 | H |
| Rear tyre | 215 | 55 | R | 16 | H |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | | |
|-----|---------------------------|--------------------------------|----------|
| [x] | FRONT MUDGUARD/RIGHT/REAR | SCRATCH WITH PAINT DAMAGE | |
| [x] | FRONT BUMPER/RIGHT/SIDE | SCRATCH WITH PAINT DAMAGE | |
| [x] | ROOF/CENTER/LEFT | SCRATCH (WITHOUT PAINT DAMAGE) | POLIEREN |

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| [x] | REAR MUDGUARD/RIGHT/REAR | DENT | | | |
|--------|--------------------------|---------------------------|---------------|-------|------------|
| Number | Code | Description | Unit price | Depr. | Total |
| 2 | I 1 i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR |
| [x] | REAR DOOR/LEFT/FRONT | SCRATCH WITH PAINT DAMAGE | | +DEUK | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 3 | 0 LU =0.00 EUR | 318.35 EUR | | 50 % | 318.35 EUR |

Others

RIM FRONT LEFT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 1 | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

RIM REAR LEFT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 1 | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|-------|--------|---|---|---|---|---|---|----|
| 190.00 | 63.00 | 318.35 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 190.00 | 63.00 | 159.18 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|-------------------|
| 253.00 | 318.35 | 0 | 571.35 |
| HOG: 0 | BG: 0 | | NA Deprec. 412.18 |
| | | | 0.00% |
| | | | TOTAL 412.18 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|-------------------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|--|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 11/07/2017 Hour : 08:40 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |