

BUQVKG

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------|----------------------------|--------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 161022 KM |
| File nr. : | 1416794 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1DOW564 / WF0HXXWPBHCK09702 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 10/07/2012 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | FORD / C-MAX | Fuel type : | DIESEL |
| Object nr. : | 709093 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | VANAS ENGINEERING NV | Co2: | 124g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | | Seats (minivan) : | 0 |
| Vehicle type : | GR.C-MAX Trend St/St 115PK | Country registration : | BELGIUM |

| | | | |
|------------------------------|------------|---------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | MONOVOLUME | Engine size: | 1560 |
| Gear box : | Manueel | Number of places: | 7 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 116 | kW: | 85 |
| Fisc HP | | Imported vehicle: | No |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

| | |
|--------------------|--|
| General condition: | |
|--------------------|--|

| | | | | |
|------------------------------|----|-----------------------|-------------------------|-----|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | | Transport licence : | | |
| Tax certificate : | | Navigation CD/SD/DVD | | |
| Fuel card : | | Car radio : | OK | [x] |
| Mobile phone kit : | | Extinguisher : | OK | [x] |
| | | Warning triangle : | OK | [x] |
| First aid kit : | OK | [x] | Oil level : | OK |
| Jack, wheelspanner : | OK | [x] | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | | | |
|------------|-----|----------|--------|-----|-----|---------|-------|-------|-----------------|---|----------|
| Wheel FL: | [x] | MICHELIN | Tyre : | OK | [x] | 4-6 / | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK | [x] | 2-4 / | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : |
| Wheel FR : | [x] | MICHELIN | Tyre : | [x] | OK | [x] | 4-6 / | Rim : | | / | Hubcap : |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK | [x] | 1.6-2 / | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : |
| Wheel RES: | [x] | MICHELIN | Tyre : | OK | | / | Rim : | | | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 215 | 55 | R | 16 | H |
| Rear tyre | 215 | 55 | R | 16 | H |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | | | |
|-----|------------------------|---------------|----------|--|
| [x] | ROOF/CENTER/RIGHT | DENT | | |
| [x] | REAR DOOR/RIGHT/CENTER | DENT | | |
| [x] | BONNET/LEFT/CENTER | DENT | | |
| [x] | BONNET/CENTER/LEFT | OTHER DAMAGES | HERSTELD | |

Interior

| | | | | |
|-----|-------------|-----------|--|--|
| [x] | BOOT LID IN | SCRATCHED | | |
|-----|-------------|-----------|--|--|

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | |
|-----|-------------------------|---------------------------|---------------|-------|------------|
| [x] | REAR BUMPER/LEFT/LEFT | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 5 LU =24.00 EUR | 211.80 EUR | | 50 % | 235.80 EUR |
| [x] | REAR DOOR/CENTER/LEFT | DENT | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 3 | 5 LU =24.00 EUR | 301.68 EUR | | 50 % | 325.68 EUR |
| [x] | WINDSCREEN/CENTER/RIGHT | WINDOW DAMAGE | | | |
| | Number Code | Description | Unit price | Depr. | Total |
| 4 | 11 i-vab-herstr-01 | WINDOW REPAIR | 58.80 EUR | | 58.80 EUR |
| [x] | FRONT BUMPER/RIGHT/SIDE | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 0 LU =0.00 EUR | 211.80 EUR | | 50 % | 211.80 EUR |

Pieces

| | Number | Code | Description | Unit price | Depr. | Total |
|---|--------|---------|-------------|------------|-------|-----------|
| 1 | 1 | SPOILER | | 50.00 EUR | 50 % | 50.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|-------|---|---|---|---|---|----|
| 261.80 | 235.80 | 325.68 | 58.80 | 0 | 0 | 0 | 0 | 0 | 0 |
| 130.90 | 117.90 | 162.84 | 58.80 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 58.80 | 823.28 | 0 | 882.08 |
| HOG: 0 | BG: 0 | | NA Deprec. 470.44 |
| | | | 0.00% |
| | | | TOTAL 470.44 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|-------------------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|--|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 08/07/2017 Hour : 12:25 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |