

www.vabfleetservices.be Date: 10/07/2017 1/5

BUSEQC

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	187666 KM
File nr. :	1416821	Mileage start / arrival:	0/0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FEX880 / WF0LXXGCBLD	M24010 /	yr of constructionr :	/
E-File nr. :		First registration :	11/06/2013
VFS-nr. :		Color :	BLUE
Make + Model :	FORD / FOCUS CLIPPER	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification:		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	88g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	FOCUS CLIP. ECOnetic Trend 88g 105PK	Country registration :	BELGIUM

		_	
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
нр:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Metallic paint:

Yes



www.vabfleetservices.be Date: 10/07/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :			Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	ОК	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Fron	t tymo	-	205	+			55		P	16	н
		[x]	Width			Не	eight		Type	Rim	Index
Wheel RES:	[x]		Tyre:	•	OK		/	Rim :		Hubcap:	
WI I DEG			m.		OV		,	D.		- TT 1	
Wheel RR:	[x]	KLÉBER	Tyre:		OK	[x]	2-4 /	Rim:		Hubcap: [x] SCRATCHED
Wheel FR:	[x]	KLÉBER	Tyre:	[x]	OK	[x]	0-1.6 /	Rim:		Hubcap: [x] SCRATCHED
Wheel RL:	[x]	KLÉBER	Tyre:		OK	[x]	2-4 /	Rim:		Hubcap: [x] SCRATCHED
Wheel FL:	[x]	KLÉBER	Tyre:		OK	[x]	0-1.6 /	Rim:		Hubcap: [x] SCRATCHED

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	Н
Rear tyre	205	55	R	16	Н

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 10/07/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

Bo								
_	dywork \& windows							
x]	REAR DOOR/RIGHT/RIGHT		SCRATCH WITH PAINT DAMAGE					
[x]	REAR BUMPER/SIDE/LEFT/FRONT		SCRATCH WITH PAINT DAMAGE					
[x]	REAR MUDGUARD/LEFT/CENTER		DENT	MEERDERE				
x]	REAR THRESHOLD/LEFT/REAR		DENT	INT				
x]	REAR DOOR/RIGHT/CENTER		SCRATCH (WITHOUT PAINT DAMAGE)	TE POLIEREN				
x]	REAR THRESHOLD/RIGHT/REAR		DENT	MET LAKSCHADE/INT				
[x]	FRONT DOOR/LEFT/REAR		SCRATCH WITH PAINT DAMAGE	RAND				
[x]	FRONT DOOR/LEFT/FRONT		DENT					
[x]	BONNET/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE					
Inte	erior							
	CARPET FL		HOLE					
[X]								
	DOOR IN REAR L		SCRATCHED					
[x]		ABLE						
[x]	DOOR IN REAR L	ABLE						
ST	DOOR IN REAR L ATUS: NOT ACCEPTA	ABLE						
x] ST	DOOR IN REAR L ATUS: NOT ACCEPTA erior	ABLE Description	SCRATCHED	Depr. Total				
x] ST	DOOR IN REAR L ATUS: NOT ACCEPTA Perior SEAT REAR L		SCRATCHED					
ST Inte	DOOR IN REAR L ATUS: NOT ACCEPTA erior SEAT REAR L Number Code	Description	SCRATCHED STAIN Unit price	-				
ST Inte	DOOR IN REAR L ATUS: NOT ACCEPTA Prior SEAT REAR L Number Code 1 I 1 i-vab-rein-07	Description	SCRATCHED STAIN Unit price 14.58 EUR					
ST Inte	DOOR IN REAR L ATUS: NOT ACCEPTA Prior SEAT REAR L Number Code 1 I 1 i-vab-rein-07 SEAT REAR RIGHT	Description CLEANING (PER 15')	SCRATCHED STAIN Unit price 14.58 EUR STAIN	Depr. Total				
	DOOR IN REAR L ATUS: NOT ACCEPTA Prior SEAT REAR L Number Code 1 I 1 i-vab-rein-07 SEAT REAR RIGHT Number Code	Description CLEANING (PER 15') Description	SCRATCHED STAIN Unit price 14.58 EUR STAIN Unit price	14.58 EUR				



www.vabfleetservices.be Date: 10/07/2017 4/5

Others

HUB CAP FR

Repair paint - LI New paint - E Depr. Total

2 0 LU =0.00 EUR 50 %

Pieces

]	Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP		30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
139.80	30.00	0	0	0	0	0	0	0	0
139.80	15.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
139.80	30.00	0		169.80
HOG: 0	BG: 0		NA Deprec.	154.80

0.00%
TOTAL 154.80



5/5

10/07/2017 www.vabfleetservices.be Date: [x] = Status Modification **Pictures:** No **CIRCUMSTANCES** NORMAL CONCLUSION Waiting time : Extra Time : $0 \min$ 0 min Towing time : $0 \min$ Reason: Reason: NOT EXECUTED: No Reason: Remark: Prices in EUR without VAT Authorized by Executed by VAB Fleet Services customer : Remark authorized customer : Date : 10/07/2017 Hour: 13:30 Company: Executed by VAB Fleet Services E-Mail: Signature authorized by customer