

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	121697 KM
File nr. :	1414484	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DFS516 / WF0MXXGBWMCA79637 /		yr of constructionr :	/
E-File nr. :		First registration :	07/05/2012
VFS-nr. :		Color :	SILVER
Make + Model :	FORD / GALAXY	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	K.U. LEUVEN - UZ LEUVEN	Co2:	139g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	GALAXY Econetic Ghia St&St DPF 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	DUNLOP	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	DUNLOP	Tyre :	[x]	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]	ANDERE	Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	Y
Rear tyre	225	50	R	17	Y

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE
[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/LEFT/REAR	DENT
[x]	REAR MUDGUARD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE

Interior

[x]	BOOT LID IN	SCRATCHED
-----	-------------	-----------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT		OTHER DAMAGES		SLECHTE HERSTELLING	
	Number	Code	Description	Unit price	Depr.	Total
0	0					
[x]	REAR DOOR/LEFT/CENTER		OTHER DAMAGES		SLECHTE HERSTELLING	
	Number	Code	Description	Unit price	Depr.	Total
0	0					
[x]	REAR DOOR/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR		382.02 EUR		50 %	382.02 EUR
[x]	FRONT MUDGUARD/LEFT/FRONT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
3	10 LU =48.00 EUR		264.21 EUR		50 %	312.21 EUR
[x]	BONNET/CENTER/RIGHT		OTHER DAMAGES		ISOLATIE	
			Repair paint - LI	New paint - E	Depr.	Total
6	2 LU =9.60 EUR		0 EUR		50 %	9.60 EUR
[x]	FRONT MUDGUARD/RIGHT/CENTER		DENT			
			Repair paint - LI	New paint - E	Depr.	Total
5	20 LU =96.00 EUR		264.21 EUR		50 %	360.21 EUR

[x]	FRONT BUMPER/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE			SCRATCH WITH PAINT DAMAGE		
	Number	Code	Description	Unit price	Depr.	Total
7	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I	2	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	29.16 EUR

RIM REAR LEFT

	Number	Code	Description	Unit price	Depr.	Total
8	I	1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR RIGHT

	Number	Code	Description	Unit price	Depr.	Total
8	I	1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

	Number	Code	Description	Unit price	Depr.	Total
8	I	1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

	Number	Code	Description	Unit price	Depr.	Total
6	1		ISOLATIE	60.00 EUR	50 %	60.00 EUR

1	2	3	4	5	6	7	8	9	10
29.16	254.16	312.21	382.02	360.21	69.60	115.56	285.00	0	0
29.16	127.08	156.10	191.01	180.10	34.80	115.56	285.00	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
429.72	1378.20	0	1807.92
HOG: 0	BG: 2		NA Deprec. 1118.82
			0.00%
			TOTAL 1118.82

APPRAISAL

www.vabfleetservices.be

Date : 07/07/2017

6/6

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 min	Waiting time :	0 min	Towing time :	0 min
		Reason :			
NOT EXECUTED : No					
Reason :					
Remark : DAKPANEEL TE REINIGEN, ZWARTE AANSLAG. [x]					

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 07/07/2017 Hour : 10:52	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	