

BTXL TJ

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	260344 KM
File nr. :	1416183	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DQR309 / WF0XXXTTFXCK68997 /		yr of constructionr :	/
E-File nr. :		First registration :	25/07/2012
VFS-nr. :		Color :	GREY
Make + Model :	FORD / TRANSIT	Fuel type :	DIESEL
Object nr. :	4894	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	COLT INTERNATIONAL NV	Co2:	204g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	TRANSIT 350M B/F MWB Amb.DPF(EU5) 125PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BESTELWAGEN	Engine size:	2198
Gear box :	Manueel	Number of places:	3
Number of gears:	6	Number of doors:	5
HP:	125	kW:	92
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	Insurance certificate :		
Warning vest :	NOK	Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
First aid kit :	OK	Oil level :	OK	[x]
Jack, wheelspanner :		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	>6 /	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6 /	Rim :	/
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	>6 /	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	75	R	16	
Rear tyre	215	75	R	16	

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 5	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR	57.35 EUR

1	2	3	4	5	6	7	8	9	10
57.35	238.76	0	0	0	0	0	0	0	0
57.35	119.38	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
57.35	238.76	0	296.11
HOG: 0	BG: 3		NA Deprec. 176.73
			0.00%
			TOTAL 176.73

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/07/2017 Hour : 10:11 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	