

BS64UK

☒ EFFECTIVE ☐ NOT EXECUTED ☐ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	22900 KM
File nr. :	1414766	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1NUZ730 / WF0WXXGCEWGG34273 /		yr of constructionr :	/
E-File nr. :		First registration :	03/05/2016
VFS-nr. :		Color :	SILVER
Make + Model :	FORD / C-MAX	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :	N	Environment Class:	EURO 6
Customer company :	ONBEKEND	Co2:	113g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1499
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
		Warning triangle :	OK
First aid kit :	OK	Oil level :	OK
Jack, wheelspanner :		Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	GOODYEAR	Tyre :	OK	4-6 /	Rim :		/	Hubcap :	
Wheel RL :	GOODYEAR	Tyre :	OK	4-6 /	Rim :		/	Hubcap :	
Wheel FR :	GOODYEAR	Tyre :	OK	4-6 /	Rim :		/	Hubcap :	
Wheel RR :	GOODYEAR	Tyre :	OK	4-6 /	Rim :		/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	M+S
Rear tyre	215	55	R	16	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	FRONT MUDGUARD/RIGHT/CENTER	CHIPS
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE

Interior

[x]	ROOF UPHOLSTERY	CARVED
-----	-----------------	--------

Accessories and others

[x]	ANTENNA	OTHER DAMAGES
-----	---------	---------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	BONNET/CENTER/LEFT/FRONT	OTHER DAMAGES	SKECHT HERST
-----	--------------------------	---------------	--------------

Number	Code	Description	Unit price	Depr.	Total
0	0				

Interior

	BOOT IN R	SCRATCHED
--	-----------	-----------

Number	Code	Description	Unit price	Depr.	Total
0	0				

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 0		NA Deprec. 0
			0.00%
			TOTAL 0

APPRAISAL

www.vabfleetservices.be

Date : 28/06/2017

4/4

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 min	Waiting time :	0 min	Towing time :	0 min
		Reason :		Reason :	
NOT EXECUTED :					
No					
Reason :					
Remark :					
[x]					

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 28/06/2017 Hour : 15:01	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	