

BUGQOO

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	44306 KM
File nr. :	1416606	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HUN316 / 3C4PFACY7FT536878 /		yr of constructionr :	/
E-File nr. :		First registration :	07/10/2014
VFS-nr. :		Color :	BLACK
Make + Model :	FIAT / FREEMONT	Fuel type :	DIESEL
Object nr. :	61120	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CLINIQUES UNIVERSITAIRES SAINT	Co2:	169g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1956
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	
Cert. of reg. / Part 1:	OK	[x]
Cert. of reg. copy / Part 2:		
Warning vest :	OK	[x]
Tax certificate :		
Fuel card :		
Mobile phone kit :		
First aid kit :	OK	[x]
Jack, wheelspanner :		

Service manual :		
Cert. of conformity :		
Insurance certificate :		
Transport licence :		
Navigation CD/SD/DVD		
Car radio :	OK	[x]
Extinguisher :	OK	[x]
Warning triangle :	OK	[x]
Oil level :	OK	[x]
Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	VREDESTEIN	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :		
Wheel RL :	[x]	VREDESTEIN	Tyre :	OK	[x]	>6 /	Rim :			/	Hubcap :		
Wheel FR :	[x]	VREDESTEIN	Tyre :	[x]	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RR :	[x]	VREDESTEIN	Tyre :		OK	[x]	>6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :		OK		/	Rim :			/	Hubcap :	

	[x]	Width	Height	Type	Rim	Index
Front tyre		225	55	R	19	V
Rear tyre		225	55	R	19	V

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/LEFT/FRONT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x] REAR DOOR/LEFT/CENTER SCRATCH WITH PAINT DAMAGE +DEUK

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] REAR DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
7 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] BONNET/CENTER/RIGHT OTHER DAMAGES ISOLATIE BINNENIN

	Repair paint - LI	New paint - E	Depr.	Total
8 0 LU =0.00 EUR	0 EUR		50 %	

	Repair paint - LI	New paint - E	Depr.	Total
8 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

[x] FRONT MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE +DEUK

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

[x] FRONT BUMPER/LEFT/SIDE SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
0	0				

[x] BONNET/CENTER/LEFT/FRONT DENT

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR

[x]	BONNET/CENTER/RIGHT/FRONT		OTHER DAMAGES		CHEMISCHE INWERKING	
	Number	Code	Description	Unit price	Depr.	Total
0	0					

[x]	FRONT BUMPER/CENTER/RIGHT			SCRATCH WITH PAINT DAMAGE		
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
8	1 ISOLATIE		50.00 EUR	50 %	50.00 EUR

1	2	3	4	5	6	7	8	9	10
190.00	318.35	431.98	110.64	290.08	211.80	318.35	74.00	0	0
190.00	159.18	215.99	110.64	145.04	105.90	159.18	37.00	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
300.64	1644.56	0	1945.20
HOG: 0	BG: 0		NA Deprec. 1122.92
			0.00%
			TOTAL 1122.92

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/07/2017 Hour : 13:14 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	