

BS11JR

☒ EFFECTIVE   
 ☐ NOT EXECUTED   
 ☒ COLLECTION   
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	130786 KM
File nr. :	1414655	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EXB839 / WF0MXXGBWMCS78300 /		yr of constructionr :	/
E-File nr. :		First registration :	11/04/2013
VFS-nr. :		Color :	GREY
Make + Model :	FORD / GALAXY	Fuel type :	DIESEL
Object nr. :	5392	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ISS NV	Co2:	139g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	GALAXY Econetic Ghia St&St DPF 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1560
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK
Jack, wheelspanner :	OK	[x]	Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	KLÉBER	Tyre :	OK	[x]	4-6 /	Rim :			/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	4-6 /	Rim :		/	Hubcap :
Wheel RR :	[x]	KLÉBER	Tyre :	OK	[x]	4-6 /	Rim :			/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	V
Rear tyre	225	50	R	17	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/RIGHT	CHIPS
[x]	FRONT MUDGUARD/RIGHT/CENTER	DENT
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE

### Interior

[x]	ROOF UPHOLSTERY	OTHER DAMAGES
[x]	BOOT LID IN	SCRATCHED

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/RIGHT/CORNER	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
2	15 LU =72.00 EUR	0 EUR		50 %	72.00 EUR
[x]	REAR MUDGUARD/RIGHT/REAR	DENT			
	Number Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT DOOR/RIGHT/CENTER	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
4	0 LU =0.00 EUR	382.02 EUR		50 %	382.02 EUR
[x]	FRONT MUDGUARD/RIGHT/REAR	DENT			
	Number Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

### Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	REAR BUMPER	411.84 EUR	50 %	411.84 EUR

1	2	3	4	5	6	7	8	9	10
0	483.84	63.00	382.02	63.00	0	0	0	0	0
0	241.92	63.00	191.01	63.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
126.00	865.86	0	<b>991.86</b>
HOG: 0	BG: 2		NA Deprec. 558.93
			0.00%
			<b>TOTAL 558.93</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

## Prices in EUR without VAT

Authorized by customer :  Remark authorized customer :  Date : 08/07/2017      Hour : 10:09 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	