

BV259F

☒ EFFECTIVE ☐ NOT EXECUTED ☐ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	146360 KM
File nr. :	1417028	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
BJ4299 / ZFA27000064345144 /		yr of constructionr :	/
E-File nr. :		First registration :	12/06/2014
VFS-nr. :		Color :	WHITE
Make + Model :	FIAT / SCUDO	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	6 [x]
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1997
Gear box :	Manueel	Number of places:	6
Number of gears:	6	Number of doors:	5
HP:	128	kW:	94
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity :
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest : OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
	Warning triangle : OK [x]
First aid kit : OK [x]	Oil level : OK [x]
Jack, wheelspanner :	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	2-4 /	Rim :	/
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	
Rear tyre	215	60	R	16	

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork l& windows

[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE		+DEUK	
			Repair paint - LI	New paint - E	Depr.	Total
2	0	LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR
[x]	REAR DOOR/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

1	2	3	4	5	6	7	8	9	10
110.64	231.15	110.64	0	0	0	0	0	0	0
110.64	115.58	110.64	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
221.28	231.15	0	452.43
HOG: 0	BG: 3		NA Deprec. 336.86
			0.00%
			TOTAL 336.86

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/07/2017 Hour : 09:38 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	