

www.vabfleetservices.be Date: 17/05/2017 1/4

B8MNH8

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Covering:

Vehicle kind:

Vehicle type:

General condition:

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 106535 KM File nr. : Mileage start / arrival: 0 / 01399460 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1DED908 / WF0LXXGCBLCG58357 / E-File nr. : First registration: 20/04/2012 Color: VFS-nr.: **GREY** Make + Model : Fuel type : FORD / FOCUS CLIPPER **DIESEL** Object nr. : Fuel: 70253 Classification: **Environment Class:** EURO 5 Customer company: Co2: **KUNST IN HUIS** 109g/km Driver : Remote controls: 2

Number keys:

Seats (minivan):

Country registration:

2[x]

BELGIUM

0

PARTIAL LEATHER

FOCUS CLIP. ECOnetic T.Titanium 115PK

VEHICLE

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown



www.vabfleetservices.be Date: 17/05/2017 2/4

Original registr. number : OK	Service manual: OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate:	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher: OK [x]
	Warning triangle: OK [x]
First aid kit: OK [x]	Oil level: OK [x]
Jack, wheelspanner :	Filled up: 0

Wheels and tyres: Summer tires

Wheel FL: Wheel RL:	[x]	MICHELIN MICHELIN	Tyre : Tyre :		OK OK		2-4 /	Rim :		/	Hubcap :	
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK		2-4 /	Rim:		/	Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RES:	[x]	MICHELIN	Tyre:		OK		/	Rim:		/	Hubcap:	
		[x]	Width			Hei	ight		Туре		Rim	Index
Fron	t tyre		215			5	55		R		16	Н

Front tyre	215	55	R	10	П
Rear tyre	215	55	R	16	Н
	·	•	·		

Remark: REPSET OK

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 17/05/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] REAR DOOR/CENTER/LEFT OTHER DAMAGES

[x] REAR MUDGUARD/LEFT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR DOOR/RIGHT/CENTER DENT

[x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

[x] FRONT BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] FRONT BUMPER/CENTER/RIGHT DENT

Interior

[x] SEAT FL SCRATCHED

[x] BOOT LID IN SCRATCHED

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
0		0	0	0
Deprec. 0	NA Depr		BG: 0	HOG: 0
.00%	0.00%			
OTAL	TOTAL			



www.vabfleetservices.be Date: 17/05/2017 4/4

[x] = Status Modification

Pictures: No

		NORMAL CONCLUSION					
	Waiting time: 0 min Reason:		Towing time : Reason :	0 min			
)							
AT							
		Executed by VAB Fleet Se	rvices				
2017 Но	our: 13:15						
<u> </u>							
2	2017 Ho	AT Hour: 13:15	AT Executed by VAB Fleet Se 2017 Hour: 13:15	Reason: Beason: Beason: Beaso			