

BWU9OG

☒ EFFECTIVE    ☐ NOT EXECUTED    ☐ COLLECTION    ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT:    EXT: DIRTY [x]
Owner :		Mileage :	177781 KM
File nr. :	1418383	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EGT748 / WF0HXXWPBHICY37704 /		yr of constructionr :	/
E-File nr. :		First registration :	28/11/2012
VFS-nr. :		Color :	BEIGE
Make + Model :	FORD / C-MAX	Fuel type :	
Object nr. :	ONBEKEND	Fuel :	
Classification :	N	Environment Class:	
Customer company :	WRAK KBC REMARKETING	Co2:	g/km
Driver :		Remote controls:	1
Covering :	LEATHER	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:		kW:	
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:
--------------------

Original registr. number :	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity :
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest : OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio :
Mobile phone kit :	Extinguisher :
First aid kit :	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	SEMPERIT	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	[x]	SEMPERIT	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	[x]	SEMPERIT	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	[x]	SEMPERIT	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	M+S
Rear tyre	215	55	R	16	M+S

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS

### Interior

[x]	BOOT LID IN	CARVED
-----	-------------	--------

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	FRONT BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	WIND SCREEN/BELOW/RIGHT	WINDOW DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

### Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	FIXATION COVER	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR

1	2	3	4	5	6	7	8	9	10
0	241.80	487.20	211.80	0	0	0	0	0	0
0	120.90	243.60	105.90	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	940.80	0	940.80
HOG: 0	BG: 0		NA Deprec. 470.40
			0.00%
			TOTAL 470.40

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : DISTRIBUTIE RIEM AF [x]		

## Prices in EUR without VAT

Authorized by customer :  Remark authorized customer :  Date : 10/07/2017      Hour : 11:06 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	