

[X] EFFECTIVE [] NOT EXECUTED

[] COLLECTION

[] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	119577 KM
File nr. :	1418158	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :	1DML252 / W0LGT6EL8C1114434 /	Mileag ref. service :	0
E-File nr. :		yr of constructionr :	/
VFS-nr. :		First registration :	22/06/2012
Make + Model :	OPEL / INSIGNIA	Color :	BLACK
Object nr. :		Fuel type :	DIESEL
Classification :		Fuel :	
Customer company :	KBC GROEP NV	Environment Class:	EURO 5
Driver :		Co2:	116g/km
Covering :	LEATHER	Remote controls:	2
Vehicle kind :	VEHICLE	Number keys :	2 [x]
Vehicle type :	INSIGNIA BER ecofl.Cosmo S/S DPF 130PK	Seats (minivan) :	0
		Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1956
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	131	kW:	96
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
General condition:		Use:	Unknown

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	Insurance certificate :		
Warning vest :	OK	Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	Warning triangle :	OK	[x]
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :		0

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel FR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RES:	[x]	ANDERE	Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	245	45	R	18	W
Rear tyre	245	45	R	18	W

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x] WINDSCREEN/CENTER/RIGHT	CHIPS
[x] FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x] FRONT DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE
[x] BONNET/CENTER/RIGHT/FRONT	CHIPS

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 0		NA Deprec. 0
			0.00%
			TOTAL 0

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 07/07/2017	Hour : 16:00
Company :	
Executed by VAB Fleet Services	
E-Mail : @	
Signature authorized by customer	