

[X] EFFECTIVE [] NOT EXECUTED

[] COLLECTION

[] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	99903 KM
File nr. :	1417026	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :	NF6186 / VF3LPHNYHES099254 /	Mileag ref. service :	0
E-File nr. :		yr of constructionr :	/
VFS-nr. :		First registration :	19/06/2014
Make + Model :	PEUGEOT / 308	Color :	RED
Object nr. :	ONBEKEND	Fuel type :	PETROL
Classification :		Fuel :	
Customer company :	ONBEKEND	Environment Class:	
Driver :		Co2:	g/km
Covering :	TISSUE	Remote controls:	2
Vehicle kind :		Number keys :	2 [x]
Vehicle type :		Seats (minivan) :	0
		Country registration :	BELGIUM

VAT over the margin - car:	Metallic paint:	Yes
Variant car:	Engine size:	1199
Gear box :	Number of places:	5
Number of gears:	Number of doors:	5
HP:	kW:	96
Fisc HP	Imported vehicle:	No
Animals transported:	Smoked in vehicle:	No
Due date vehicle inspection:	Extra set of tires:	No
	Use:	Unknown
General condition:		

Original registr. number :			Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :			Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK	[x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK	[x]
			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :		/ Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED / Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED / Hubcap :
Wheel RES:	[x]	MICHELIN	Tyre :	OK	[x]	>6 /	Rim :		/ Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/ Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/CENTER	DENT
[x] FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x] BONNET/CENTER/RIGHT	CHIPS

Interior

[x] CENTER CONSOLE	SCRATCHED
--------------------	-----------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR MUDGUARD/RIGHT/CENTER	DENT			
	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
[x] FRONT BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE			
Number Code	Description	Unit price	Depr.	Total
1 I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

Others

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
115.56	308.20	95.00	0	0	0	0	0	0	0
115.56	154.10	95.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
210.56	308.20	0	518.76
HOG: 0	BG: 0		NA Deprec. 364.66
			0.00%
			TOTAL 364.66

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 08/07/2017	Hour : 09:23
Company :	
Executed by VAB Fleet Services	
E-Mail : @	
Signature authorized by customer	