

[X] EFFECTIVE [ ] NOT EXECUTED

[X] COLLECTION

[ ] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	86465 KM
File nr. :	1418350	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EWE882 / VF15RJL0H48730199 /		yr of constructionr :	/
E-File nr. :		First registration :	05/04/2013
VFS-nr. :		Color :	WHITE
Make + Model :	RENAULT / CLIO	Fuel type :	DIESEL
Object nr. :	49284	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	RANDSTAD GROUP BELGIUM NV	Co2:	83g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	CLIO IV BER e-Expression St&St 90PK	Country registration :	BELGIUM

VAT over the margin - car:	Metallic paint:
Variant car:	Engine size: 1461
Gear box :	Number of places: 5
Number of gears:	Number of doors: 5
HP:	kW: 66
Fisc HP	Imported vehicle:
Animals transported:	Smoked in vehicle:
Due date vehicle inspection:	Extra set of tires:
	Use: Unknown
General condition:	

Original registr. number :	OK	Service manual :
Cert. of reg. / Part 1:		Cert. of conformity : OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :
Warning vest :	OK [x]	Transport licence :
Tax certificate :		Navigation CD/SD/DVD
Fuel card :		Car radio :
Mobile phone kit :		Extinguisher : OK [x]
First aid kit :	OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	OK [x]	Oil level : OK [x]
		Filled up : 0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :	[x]	/	Hubcap :	[x]	SCRATCHED
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :	[x]	/	Hubcap :	[x]	SCRATCHED
Wheel FR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :	[x]	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :	[x]	/	Hubcap :	[x]	SCRATCHED
Wheel RES:	[x]		Tyre :	OK	/		Rim :		/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	185	65	R	15	H
Rear tyre	185	65	R	15	H

Remark :

## Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)
[x] REAR DOOR/LEFT/CENTER	DENT
[x] FRONT DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x] FRONT MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x] BONNET/CENTER/LEFT/FRONT	CHIPS
[x] BONNET/CENTER/RIGHT/FRONT	DENT

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x] REAR DOOR/CENTER/RIGHT	DENT			
		Repair paint - LI	New paint - E	Depr. Total
<b>3</b> 15 LU =72.00 EUR	241.34 EUR			50 % 313.34 EUR
[x] REAR MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr. Total
<b>4</b> 0 LU =0.00 EUR	246.56 EUR			50 % 246.56 EUR
		Repair paint - LI	New paint - E	Depr. Total
<b>4</b> 15 LU =72.00 EUR	0 EUR			50 % 72.00 EUR
[x] FRONT BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr. Total
<b>2</b> 0 LU =0.00 EUR	169.44 EUR			50 % 169.44 EUR

### Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
<b>1</b>	I 3	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR	34.41 EUR
		HUB CAP REAR RIGHT			
		Repair paint - LI	New paint - E	Depr.	Total
<b>5</b>	0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

**Pieces**

Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

1	2	3	4	5	6	7	8	9	10
34.41	169.44	313.34	318.56	48.00	0	0	0	0	0
34.41	84.72	156.67	159.28	24.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
34.41	849.34	0	883.75
HOG: 0	BG: 1	NA Deprec.	459.08
		0.00%	
		TOTAL	459.08

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 13/07/2017	Hour : 12:20
Company :	
Executed by VAB Fleet Services	
E-Mail : @	
Signature authorized by customer	