

BWRQTF

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	55140 KM
File nr. :	1418332	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FBM276 / VF1JZ140648764583 /		yr of constructionr :	/
E-File nr. :		First registration :	16/05/2013
VFS-nr. :		Color :	SILVER
Make + Model :	RENAULT / SCENIC	Fuel type :	DIESEL
Object nr. :	49284	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	RANDSTAD GROUP BELGIUM NV	Co2:	105g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	SCENIC Energ.Expression 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	
Cert. of reg. / Part 1:		
Cert. of reg. copy / Part 2:	OK	[x]
Warning vest :	OK	[x]
Tax certificate :		
Fuel card :		
Mobile phone kit :		
First aid kit :	OK	[x]
Jack, wheelspanner :	OK	[x]
Service manual :		
Cert. of conformity :	OK	
Insurance certificate :		
Transport licence :		
Navigation CD/SD/DVD	OK	[x]
Car radio :	OK	[x]
Extinguisher :	OK	[x]
Warning triangle :	OK	[x]
Oil level :	OK	[x]
Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4 /	Rim :		/	Hubcap : [x] SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap : [x] SCRATCHED	
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :	

	[x]	Width	Height	Type	Rim	Index
Front tyre		205	60	R	16	H
Rear tyre		205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT

SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] FRONT DOOR/LEFT/CENTER

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] FRONT BUMPER/LEFT

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	318.35	60.00	0	0	0	0	0	0	0
105.90	159.18	30.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	590.15	0	590.15
HOG: 0	BG: 0		NA Deprec. 295.08
			0.00%
			TOTAL 295.08

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/07/2017 Hour : 12:21 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	