

BUNVCV

☒ EFFECTIVE    ☐ NOT EXECUTED    ☒ COLLECTION    ☐ DELIVERY

[x] = Status Modification

|                               |                               |                          |                               |
|-------------------------------|-------------------------------|--------------------------|-------------------------------|
| Commissionar :                | KBC REMARKETING               | Cleanliness :            | INT: DIRTY [x] EXT: CLEAN [x] |
| Owner :                       |                               | Mileage :                | 166104 KM                     |
| File nr. :                    | 1416734                       | Mileage start / arrival: | 0 / 0                         |
| Reg number / Chassis / Ref :  |                               | Mileag ref. service :    | 0                             |
| 1FVX840 / VF1KZ1A0749933419 / |                               | yr of constructionr :    | /                             |
| E-File nr. :                  |                               | First registration :     | 13/11/2013                    |
| VFS-nr. :                     |                               | Color :                  | SILVER                        |
| Make + Model :                | RENAULT / MEGANE BREAK        | Fuel type :              | DIESEL                        |
| Object nr. :                  | 69117                         | Fuel :                   |                               |
| Classification :              |                               | Environment Class:       | EURO 5                        |
| Customer company :            | VSK ELECTRONICS NV            | Co2:                     | 104g/km                       |
| Driver :                      |                               | Remote controls:         | 3                             |
| Covering :                    | TISSUE                        | Number keys :            | 2 [x]                         |
| Vehicle kind :                | VEHICLE                       | Seats (minivan) :        | 0                             |
| Vehicle type :                | MEGANE GT TomTom Edition 90PK | Country registration :   | BELGIUM                       |

|                              |         |                     |         |
|------------------------------|---------|---------------------|---------|
| VAT over the margin - car:   | No      | Metallic paint:     | Yes     |
| Variant car:                 | BREAK   | Engine size:        | 1461    |
| Gear box :                   | Manueel | Number of places:   | 5       |
| Number of gears:             | 5       | Number of doors:    | 5       |
| HP:                          | 90      | kW:                 | 66      |
| Fisc HP                      |         | Imported vehicle:   |         |
| Animals transported:         | No      | Smoked in vehicle:  | Yes     |
| Due date vehicle inspection: |         | Extra set of tires: | No      |
|                              |         | Use:                | Unknown |

|                    |  |
|--------------------|--|
| General condition: |  |
|--------------------|--|

|                              |                         |
|------------------------------|-------------------------|
| Original registr. number :   | Service manual :        |
| Cert. of reg. / Part 1:      | Cert. of conformity :   |
| Cert. of reg. copy / Part 2: | Insurance certificate : |
| Warning vest :               | Transport licence :     |
| Tax certificate :            | Navigation CD/SD/DVD    |
| Fuel card :                  | Car radio :             |
| Mobile phone kit :           | Extinguisher :          |
| First aid kit :              | Warning triangle :      |
| Jack, wheelspanner :         | Oil level :             |
|                              | Filled up : 0           |

## Wheels and tyres: Summer tires

|            |     |          |        |     |     |       |       |       |          |          |           |           |
|------------|-----|----------|--------|-----|-----|-------|-------|-------|----------|----------|-----------|-----------|
| Wheel FL:  | [x] | GOODYEAR | Tyre : | OK  | [x] | 2-4 / | Rim : | /     | Hubcap : | [x]      | SCRATCHED |           |
| Wheel RL : | [x] | GOODYEAR | Tyre : | OK  | [x] | 2-4 / | Rim : | /     | Hubcap : | [x]      | SCRATCHED |           |
| Wheel FR : | [x] | GOODYEAR | Tyre : | [x] | OK  | [x]   | 2-4 / | Rim : | /        | Hubcap : | [x]       | SCRATCHED |
| Wheel RR : | [x] | GOODYEAR | Tyre : | OK  | [x] | 2-4 / | Rim : | /     | Hubcap : | [x]      | SCRATCHED |           |
| Wheel RES: | [x] |          | Tyre : | OK  |     | /     | Rim : | /     | Hubcap : |          |           |           |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 195   | 65     | R    | 15  | V     |
| Rear tyre  | 195   | 65     | R    | 15  | V     |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |   |          |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL:  |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: |  | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR BUMPER/LEFT/CORNER SCRATCH WITH PAINT DAMAGE

### Interior

[x] DASHBORD OTHER DAMAGES

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

|     |                         |      |                   |               |            |
|-----|-------------------------|------|-------------------|---------------|------------|
| [x] | FRONT DOOR/RIGHT/CENTER | DENT |                   |               |            |
|     |                         |      | Repair paint - LI | New paint - E | Depr.      |
|     |                         |      |                   |               | Total      |
| 3   | 0 LU =0.00 EUR          |      | 318.35 EUR        |               | 50 %       |
|     |                         |      |                   |               | 318.35 EUR |

|     |                           |      |                   |               |            |
|-----|---------------------------|------|-------------------|---------------|------------|
| [x] | BONNET/CENTER/RIGHT/FRONT | DENT |                   |               |            |
|     |                           |      | Repair paint - LI | New paint - E | Depr.      |
|     |                           |      |                   |               | Total      |
| 2   | 0 LU =0.00 EUR            |      | 290.08 EUR        |               | 50 %       |
|     |                           |      |                   |               | 290.08 EUR |

### Interior

|     |                 |               |                   |               |           |
|-----|-----------------|---------------|-------------------|---------------|-----------|
| [x] | DOOR IN FL      | OTHER DAMAGES |                   |               |           |
|     |                 |               | Repair paint - LI | New paint - E | Depr.     |
|     |                 |               |                   |               | Total     |
| 1   | 5 LU =24.00 EUR |               | 0 EUR             |               | 50 %      |
|     |                 |               |                   |               | 24.00 EUR |

|     |                 |      |                   |               |           |
|-----|-----------------|------|-------------------|---------------|-----------|
| [x] | DOOR IN REAR L  | HOLE |                   |               |           |
|     |                 |      | Repair paint - LI | New paint - E | Depr.     |
|     |                 |      |                   |               | Total     |
| 1   | 5 LU =24.00 EUR |      | 0 EUR             |               | 50 %      |
|     |                 |      |                   |               | 24.00 EUR |

|     |                 |        |                   |               |           |
|-----|-----------------|--------|-------------------|---------------|-----------|
| [x] | BOOT LID IN     | CARVED |                   |               |           |
|     |                 |        | Repair paint - LI | New paint - E | Depr.     |
|     |                 |        |                   |               | Total     |
| 1   | 5 LU =24.00 EUR |        | 0 EUR             |               | 50 %      |
|     |                 |        |                   |               | 24.00 EUR |

### Others

CLEANLINESS INTERIOR

| Number | Code | Description                          | Unit price        | Depr.     | Total     |
|--------|------|--------------------------------------|-------------------|-----------|-----------|
| 1      | I 3  | specifiek-per-kwartier-a-vab-rein-03 | CLEANING INTERIOR | 14.58 EUR | 43.74 EUR |

HUB CAP FL

|   |                |  |                   |               |       |
|---|----------------|--|-------------------|---------------|-------|
|   |                |  | Repair paint - LI | New paint - E | Depr. |
|   |                |  |                   |               | Total |
| 4 | 0 LU =0.00 EUR |  |                   |               | 50 %  |

HUB CAP REAR RIGHT

|                  | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|-------|
| 4 0 LU =0.00 EUR |                   |               | 50 %  |       |

HUB CAP FR

|                  | Repair paint - LI | New paint - E | Depr. | Total |
|------------------|-------------------|---------------|-------|-------|
| 4 0 LU =0.00 EUR |                   |               | 50 %  |       |

## Pieces

| Number | Code | Description     | Unit price | Depr. | Total     |
|--------|------|-----------------|------------|-------|-----------|
| 1      | 1    | UPHOLSTERY DOOR | 90.00 EUR  | 50 %  | 90.00 EUR |
| Number | Code | Description     | Unit price | Depr. | Total     |
| 1      | 1    | BEKLEDING       | 40.00 EUR  | 50 %  | 40.00 EUR |
| Number | Code | Description     | Unit price | Depr. | Total     |
| 1      | 1    | RAAGELEIDER     | 40.00 EUR  | 50 %  | 40.00 EUR |
| Number | Code | Description     | Unit price | Depr. | Total     |
| 4      | 1    | WHEEL CAP       | 30.00 EUR  | 50 %  | 30.00 EUR |
| Number | Code | Description     | Unit price | Depr. | Total     |
| 4      | 1    | WHEEL CAP       | 30.00 EUR  | 50 %  | 30.00 EUR |
| Number | Code | Description     | Unit price | Depr. | Total     |
| 4      | 1    | WHEEL CAP       | 30.00 EUR  | 50 %  | 30.00 EUR |

| 1      | 2      | 3      | 4     | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|-------|---|---|---|---|---|----|
| 285.74 | 290.08 | 318.35 | 90.00 | 0 | 0 | 0 | 0 | 0 | 0  |
| 164.74 | 145.04 | 159.18 | 45.00 | 0 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                   |
|------------|-------------|---------|-------------------|
| 43.74      | 940.43      | 0       | 984.17            |
| HOG: 0     | BG: 0       |         | NA Deprec. 513.96 |
|            |             |         | 0.00%             |
|            |             |         | TOTAL 513.96      |

# APPRAISAL

**www.vabfleetservices.be**

**Date : 11/07/2017**

5/5

**[x] = Status Modification**

**Pictures :** No

## CIRCUMSTANCES

|                    |                      |                     |
|--------------------|----------------------|---------------------|
| Extra Time : 0 min | Waiting time : 0 min | Towing time : 0 min |
|                    | Reason :             | Reason :            |
| NOT EXECUTED : No  |                      |                     |
| Reason :           |                      |                     |
| Remark :           |                      |                     |

**Prices in EUR without VAT**

|                                                                                                                                |                                |
|--------------------------------------------------------------------------------------------------------------------------------|--------------------------------|
| <b>Authorized by customer :</b>                                                                                                | Executed by VAB Fleet Services |
| <b>Remark authorized customer :</b>                                                                                            |                                |
| <b>Date :</b> 11/07/2017 <b>Hour :</b> 10:25                                                                                   |                                |
| <b>Company :</b><br>Executed by VAB Fleet Services<br><b>E-Mail :</b> @                                                        |                                |
| <b>Signature authorized by customer</b><br> |                                |