

BSWO9C

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------|--|--------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 120681 KM |
| File nr. : | 1415362 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1FCW623 / VF1JZ14M648909878 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 28/05/2013 |
| VFS-nr. : | | Color : | BURGUNDY |
| Make + Model : | RENAULT / GRAND SCENIC | Fuel type : | DIESEL |
| Object nr. : | | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | BELGACOM INS/FLEET NV | Co2: | 105g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | GR.SCENIC Energ.Expression 5Pl.FAP 110PK | Country registration : | BELGIUM |

| | | | |
|------------------------------|---------|---------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | | Engine size: | 1461 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 110 | kW: | 81 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | |
| Due date vehicle inspection: | | Extra set of tires: | |
| | | Use: | Unknown |
| General condition: | | | |

| | | | | | |
|-------------------------------------|----|-----|--------------------------------|----|-----|
| Original registr. number : | OK | | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | OK | [x] | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | | | Insurance certificate : | | |
| Warning vest : | | | Transport licence : | | |
| Tax certificate : | | | Navigation CD/SD/DVD | | |
| Fuel card : | | | Car radio : | OK | [x] |
| Mobile phone kit : | | | Extinguisher : | OK | [x] |
| | | | Warning triangle : | OK | [x] |
| First aid kit : | OK | [x] | Oil level : | OK | [x] |
| Jack, wheelspanner : | OK | [x] | Filled up : | 0 | |

Wheels and tyres: Summer tires

| | | | | | | | | | | | | |
|-------------------|-----|--------|---------------|-----|-----|-------|--------------|--------------|---|-----------------|-----------------|--|
| Wheel FL : | [x] | KLÉBER | Tyre : | OK | [x] | 4-6 / | Rim : | | / | Hubcap : | | |
| Wheel RL : | [x] | KLÉBER | Tyre : | OK | [x] | 2-4 / | Rim : | | / | Hubcap : | | |
| Wheel FR : | [x] | KLÉBER | Tyre : | [x] | OK | [x] | 4-6 / | Rim : | | / | Hubcap : | |
| Wheel RR : | [x] | KLÉBER | Tyre : | OK | [x] | 2-4 / | Rim : | | / | Hubcap : | | |
| Wheel RES: | [x] | ANDERE | Tyre : | OK | [x] | >6 / | Rim : | | / | Hubcap : | | |

| | | | | | | |
|-------------------|-----|--------------|---------------|-------------|------------|--------------|
| | [x] | Width | Height | Type | Rim | Index |
| Front tyre | | 205 | 60 | R | 16 | W |
| Rear tyre | | 205 | 60 | R | 16 | W |

Remark :

Wheels and tyres:

| | | | | | | |
|------------|--------|----|---|-------|---|----------|
| Wheel FL: | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | |
|-----|---------------------------|---------------------------|
| [x] | REAR DOOR/RIGHT/RIGHT | SCRATCH WITH PAINT DAMAGE |
| [x] | REAR MUDGUARD/LEFT/FRONT | DENT |
| [x] | REAR DOOR/LEFT/CENTER | DENT |
| [x] | REAR DOOR/LEFT/FRONT | SCRATCH WITH PAINT DAMAGE |
| [x] | BONNET/CENTER/RIGHT/FRONT | CHIPS |
| [x] | FRONT BUMPER/LEFT | SCRATCH WITH PAINT DAMAGE |
| [x] | FRONT BUMPER/RIGHT/CORNER | SCRATCH WITH PAINT DAMAGE |

Interior

| | | |
|-----|-------------|-----------|
| [x] | BOOT LID IN | SCRATCHED |
|-----|-------------|-----------|

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | |
|-----|-----------------------------|---------------------------|---------------|------------|
| [x] | REAR BUMPER/CENTER/LEFT | SCRATCH WITH PAINT DAMAGE | MEERDERE | |
| | | Repair paint - LI | New paint - E | Depr. |
| | | | | Total |
| 2 | 0 LU =0.00 EUR | 211.80 EUR | 50 % | 211.80 EUR |
| [x] | FRONT DOOR/RIGHT/CENTER | SCRATCH WITH PAINT DAMAGE | | |
| | | Repair paint - LI | New paint - E | Depr. |
| | | | | Total |
| 3 | 0 LU =0.00 EUR | 318.35 EUR | 50 % | 318.35 EUR |
| [x] | FRONT THRESHOLD/RIGHT/FRONT | DENT | | |
| | | Repair paint - LI | New paint - E | Depr. |
| | | | | Total |
| 4 | 20 LU =96.00 EUR | 310.50 EUR | 50 % | 406.50 EUR |

Interior

| | | | | |
|-----|-------------------|--------------------|------------|-----------|
| [x] | SEAT REAR L | STAIN | | |
| | Number Code | Description | Unit price | Depr. |
| | | | | Total |
| 1 | I 1 i-vab-rein-07 | CLEANING (PER 15') | 14.58 EUR | 14.58 EUR |
| [x] | SEAT REAR RIGHT | STAIN | | |
| | Number Code | Description | Unit price | Depr. |
| | | | | Total |
| 1 | I 1 i-vab-rein-07 | CLEANING (PER 15') | 14.58 EUR | 14.58 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|--------|--------|--------|---|---|---|---|---|----|
| 29.16 | 211.80 | 318.35 | 406.50 | 0 | 0 | 0 | 0 | 0 | 0 |
| 29.16 | 105.90 | 159.18 | 203.25 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|-------------------|
| 29.16 | 936.65 | 0 | 965.81 |
| HOG: 0 | BG: 0 | | NA Deprec. 497.48 |
| | | | 0.00% |
| | | | TOTAL 497.48 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

| | | |
|-------------------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|--|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 06/07/2017 Hour : 14:24 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |