

BU80F1

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	71689 KM
File nr. :	1416405	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FFD385 / VF1JZNAA649155143 /		yr of constructionr :	/
E-File nr. :		First registration :	12/06/2013
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / GRAND SCENIC	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	AGC AUTOMOTIVE EUROPE	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	GRAND SCENIC Bose Ed.5pl.130PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	131	kW:	96
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK			Service manual :	OK	[x]
Cert. of reg. / Part 1:				Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]		Insurance certificate :		
Warning vest :				Transport licence :		
Tax certificate :				Navigation CD/SD/DVD	OK	[x]
Fuel card :				Car radio :	OK	[x]
Mobile phone kit :				Extinguisher :	OK	[x]
				Warning triangle :	OK	[x]
First aid kit :	OK	[x]		Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :	

	[x]	Width	Height	Type	Rim	Index
Front tyre		205	55	R	17	V
Rear tyre		205	55	R	17	V

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR THRESHOLD/RIGHT/REAR		DENT		
		Repair paint - LI	New paint - E	Depr.	Total
2	50 LU =240.00 EUR	0 EUR	414.00 EUR	50 %	654.00 EUR

[x]	FRONT BUMPER/RIGHT/SIDE		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1 DOORSTEP		250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	904.00	190.00	0	0	0	0	0	0	0
105.90	452.00	190.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
190.00	1115.80	0	1305.80
HOG: 0	BG: 0		NA Deprec. 747.90
			0.00%
			TOTAL 747.90

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 10/07/2017 Hour : 11:03 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	