

BSMF8V

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	160529 KM
File nr. :	1415142	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CUK330 / VF1KW2HB646937211 /		yr of constructionr :	/
E-File nr. :		First registration :	01/03/2012
VFS-nr. :		Color :	BLUE
Make + Model :	RENAULT / KANGOO	Fuel type :	DIESEL
Object nr. :	12290	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ALKEN MAES NV	Co2:	140g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	KANGOO 2PLC Dynamique FAP 109PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	109	kW:	80
Fisc HP		Imported vehicle:	
Animals transported:	Yes	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK			Service manual :			
Cert. of reg. / Part 1:				Cert. of conformity :	OK		
Cert. of reg. copy / Part 2:	OK	[x]		Insurance certificate :			
Warning vest :	OK	[x]		Transport licence :			
Tax certificate :				Navigation CD/SD/DVD	OK	[x]	
Fuel card :				Car radio :	OK	[x]	
Mobile phone kit :				Extinguisher :	OK	[x]	
				Warning triangle :	OK	[x]	
First aid kit :	OK	[x]		Oil level :	OK	[x]	
Jack, wheelspanner :	OK	[x]		Filled up :	0		

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :		
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :		
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :		

	[x]	Width	Height	Type	Rim	Index
Front tyre		205	55	R	16	H
Rear tyre		205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/LEFT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
2	10 LU =48.00 EUR	238.76 EUR		50 %	286.76 EUR
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	158.85 EUR		50 %	158.85 EUR

1	2	3	4	5	6	7	8	9	10
158.85	286.76	0	0	0	0	0	0	0	0
79.42	143.38	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	445.61	0	445.61
HOG: 0	BG: 3		NA Deprec. 222.80
			0.00%
			TOTAL 222.80

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 10/07/2017 Hour : 13:53 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	