

[X] EFFECTIVE [ ] NOT EXECUTED

[X] COLLECTION

[ ] DELIVERY

[x] = Status Modification

|                               |                       |                          |                               |
|-------------------------------|-----------------------|--------------------------|-------------------------------|
| Commissionar :                | KBC REMARKETING       | Cleanliness :            | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner :                       |                       | Mileage :                | 130984 KM                     |
| File nr. :                    | 1422237               | Mileage start / arrival: | 0 / 0                         |
| Reg number / Chassis / Ref :  |                       | Mileag ref. service :    | 0                             |
| 1DNO495 / WAUZZZ8X8DB001729 / |                       | yr of constructionr :    | /                             |
| E-File nr. :                  |                       | First registration :     | 02/07/2012                    |
| VFS-nr. :                     |                       | Color :                  | BLACK                         |
| Make + Model :                | AUDI / A1             | Fuel type :              | DIESEL                        |
| Object nr. :                  | 46543                 | Fuel :                   |                               |
| Classification :              |                       | Environment Class:       | EURO 5                        |
| Customer company :            | ALTRAN SA             | Co2:                     | 99g/km                        |
| Driver :                      |                       | Remote controls:         | 2                             |
| Covering :                    | TISSUE                | Number keys :            | 2 [x]                         |
| Vehicle kind :                | VEHICLE               | Seats (minivan) :        | 0                             |
| Vehicle type :                | A1 SB Attraction 90PK | Country registration :   | BELGIUM                       |

|                              |         |                     |         |
|------------------------------|---------|---------------------|---------|
| VAT over the margin - car:   | No      | Metallic paint:     | Yes     |
| Variant car:                 |         | Engine size:        | 1598    |
| Gear box :                   | Manueel | Number of places:   | 5       |
| Number of gears:             | 5       | Number of doors:    | 5       |
| HP:                          | 90      | kW:                 | 66      |
| Fisc HP                      |         | Imported vehicle:   | No      |
| Animals transported:         | No      | Smoked in vehicle:  | No      |
| Due date vehicle inspection: |         | Extra set of tires: | No      |
| General condition:           |         | Use:                | Unknown |

|                              |        |                         |    |     |
|------------------------------|--------|-------------------------|----|-----|
| Original registr. number :   | OK     | Service manual :        | OK | [x] |
| Cert. of reg. / Part 1:      |        | Cert. of conformity :   | OK |     |
| Cert. of reg. copy / Part 2: | OK [x] | Insurance certificate : |    |     |
| Warning vest :               | OK [x] | Transport licence :     |    |     |
| Tax certificate :            |        | Navigation CD/SD/DVD    |    |     |
| Fuel card :                  |        | Car radio :             | OK | [x] |
| Mobile phone kit :           |        | Extinguisher :          | OK | [x] |
| First aid kit :              | OK [x] | Warning triangle :      | OK | [x] |
| Jack, wheelspanner :         |        | Oil level :             | OK | [x] |
|                              |        | Filled up :             |    | 0   |

## Wheels and tyres: Summer tires

|            |     |             |        |    |     |       |       |     |                            |
|------------|-----|-------------|--------|----|-----|-------|-------|-----|----------------------------|
| Wheel FL:  | [x] | FULDA       | Tyre : | OK | [x] | 4-6 / | Rim : | /   | Hubcap :                   |
| Wheel RL : | [x] | CONTINENTAL | Tyre : | OK | [x] | 2-4 / | Rim : | /   | Hubcap :                   |
| Wheel FR : | [x] | FULDA       | Tyre : | OK | [x] | 4-6 / | Rim : | /   | Hubcap :                   |
| Wheel RR : | [x] | CONTINENTAL | Tyre : | OK | [x] | 2-4 / | Rim : | [x] | WHEEL SCRATCHED / Hubcap : |
| Wheel RES: | [x] |             | Tyre : | OK | /   |       | Rim : |     | Hubcap :                   |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205   | 55     | R    | 15  | V     |
| Rear tyre  | 205   | 55     | R    | 15  | V     |

Remark :

## Wheels and tyres:

|            |        |    |   |       |   |          |
|------------|--------|----|---|-------|---|----------|
| Wheel FL:  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :



## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

|     |                              |                           |                      |              |              |
|-----|------------------------------|---------------------------|----------------------|--------------|--------------|
| [x] | REAR BUMPER/SIDE/RIGHT/FRONT | SCRATCH WITH PAINT DAMAGE |                      |              |              |
|     |                              | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 2   | 0 LU =0.00 EUR               | 169.44 EUR                |                      | 50 %         | 169.44 EUR   |
| [x] | REAR MUDGUARD/RIGHT/FRONT    | SCRATCH WITH PAINT DAMAGE |                      |              |              |
|     |                              | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 2   | 0 LU =0.00 EUR               | 246.56 EUR                |                      | 50 %         | 246.56 EUR   |
| [x] | REAR DOOR/RIGHT/CENTER       | SCRATCH WITH PAINT DAMAGE |                      |              |              |
|     |                              | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 2   | 0 LU =0.00 EUR               | 254.68 EUR                |                      | 50 %         | 254.68 EUR   |
| [x] | FRONT DOOR/RIGHT/CENTER      | SCRATCH WITH PAINT DAMAGE |                      |              |              |
|     |                              | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 2   | 0 LU =0.00 EUR               | 254.68 EUR                |                      | 50 %         | 254.68 EUR   |
| [x] | FRONT BUMPER/LEFT/SIDE       | SCRATCH WITH PAINT DAMAGE |                      |              |              |
|     |                              | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 1   | 0 LU =0.00 EUR               | 169.44 EUR                |                      | 50 %         | 169.44 EUR   |

|     |                |                          |                      |              |              |
|-----|----------------|--------------------------|----------------------|--------------|--------------|
| [x] | BACK SHELF     | OTHER DAMAGES            |                      |              |              |
|     |                | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 3   | 0 LU =0.00 EUR | 0 EUR                    |                      | 50 %         |              |

| Number | Code | Description | Unit price | Depr. | Total    |
|--------|------|-------------|------------|-------|----------|
| 3      | 1    | OPHANGKOORD | 5.00 EUR   | 50 %  | 5.00 EUR |

| 1      | 2      | 3    | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|------|---|---|---|---|---|---|----|
| 169.44 | 925.36 | 5.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |
| 84.72  | 462.68 | 2.50 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                     |
|------------|-------------|---------|---------------------|
| 0          | 1099.80     | 0       | 1099.80             |
| HOG: 0     | BG: 1       |         | NA Deprec. 549.90   |
|            |             |         | 0.00%               |
|            |             |         | <b>TOTAL 549.90</b> |



[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|                    |                                  |                                 |
|--------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min | Waiting time : 0 min<br>Reason : | Towing time : 0 min<br>Reason : |
| NOT EXECUTED : No  |                                  |                                 |
| Reason :           |                                  |                                 |
| Remark :           |                                  |                                 |

Prices in EUR without VAT

|   |                                |
|---|--------------------------------|
| Authorized by customer :  | Executed by VAB Fleet Services |
| Remark authorized customer :  |                                |
| Date : 26/07/2017   | Hour : 12:02                   |
| Company :   |                                |
| Executed by VAB Fleet Services  |                                |
| E-Mail : @  |                                |
| Signature authorized by customer  |                                |
|  |                                |