

www.vabfleetservices.be Date: 24/07/2017 1/5

C06KZG

[X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness:	INT: DIRTY [x] EXT: CLEAN [x]
Owner:		Mileage :	172813 KM
File nr. :	1421013	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GTF472 / VF17R040H50627	008 /	yr of constructionr :	/
E-File nr. :		First registration :	23/04/2014
VFS-nr. :		Color :	SILVER
Make + Model :	RENAULT / CLIO	Fuel type :	DIESEL
Object nr. :	7569	Fuel :	
Classification:	A	Environment Class:	EURO 5
Customer company :	LA WILLIAM NV	Co2:	168g/km
Driver :		Remote controls:	1
Covering:	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

Variant car:	BREAK	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	75	kW:	55
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Metallic paint:

Yes



www.vabfleetservices.be Date: 24/07/2017 2/5

Original registr. number :	OK			Service manual :			
Cert. of reg. / Part 1:	OK	[x]		Cert. of conformity :	OK		
Cert. of reg. copy / Part 2:				Insurance certificate :			
Warning vest:	OK	[x]		Transport licence :			
Tax certificate :				Navigation CD/SD/DVD			
Fuel card :				Car radio :			
Mobile phone kit :				Extinguisher :	OK	[x]	
				Warning triangle :	OK	[x]	
First aid kit :	OK	[x]		Oil level :	OK	[x]	
Jack, wheelspanner :	OK	[x]		Filled up :	0		

### Wheels and tyres: Summer tires

	t tyre	[x]	Width		]	Height		Type		Rim	Index
Wheel RES:	[x]		Tyre:	OK		/	Rim:			Hubcap:	
Wheel RR:	[x]	GOODYEAR	Tyre:	OK	[x	] 2-4/	Rim:		,	Hubcap: [x	] SCRATCHED
Wheel FR:	[x]	GOODYEAR	Tyre:	x] OK	[x	] 1.6-2/	Rim:	[x]	,	Hubcap: [x	SCRATCHED
Wheel RL:	[x]	GOODYEAR	Tyre:	OK	[x	] 2-4/	Rim:		,	<b>Hubcap:</b> [x]	SCRATCHED
Wheel FL:	[x]	GOODYEAR	Tyre:	OK	[x	] 1.6-2/	Rim:		,	Hubcap: [x	SCRATCHED

[x]	Width	Height	Type	Rim	Index
Front tyre	185	65	R	15	T
Rear tyre	185	65	R	15	T

Remark:

### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 24/07/2017 3/5

#### STATUS: ACCEPTABLE / USAGE DAMAGE

odywork \& windows					
REAR BUMPER/LEFT/LEFT		SCRATCH WITH PAIN	T DAMAGE		
] REAR MUDGUARD/LEFT/CENTER		CHIPS			
REAR DOOR/LEFT/CENTER		WINDOW DAMAGE			
REAR DOOR/RIGHT/CENTER		DENT			
nterior					
BOOT LID IN		CARVED			
STATUS: NOT ACCEPTAB	LE				
odywork \& windows					
] WINDSCREEN/RIGHT		WINDOW DAMAGE			
Number Code	Description		Unit price	Depr.	Total
4 I 1 i-vab-herstr-01	WINDOW REPAIR		58.80 EUR		58.80 EUR
BONNET/CENTER/RIGHT/FRONT		OTHER DAMAGES			
Number Code	Description		Unit price	Depr.	Total
3 I 1 i-vab-ander-01	REPAIR (PER 15')		18.74 EUR		18.74 EUR
FRONT BUMPER/CENTER/RIGHT		SCRATCH WITH PAIN	T DAMAGE		
	Repair paint - LI	New paint - E		Depr.	Total
2 0 LU =0.00 EUR	169.44 EUR			50 %	169.44 EUR
thers					
CLEANLINESS INTERIOR					
Number Code	Description		Unit price	Depr.	Total
1 I 5 personenwagen-a-vab-rein-02	CLEANING INTERIOR		11.47 EUR		57.35 EUR
HUB CAP FL					
	Repair paint - LI	New paint - E		Depr.	Total
5 0 LU =0.00 EUR				50 %	
HUB CAP FR					
	Repair paint - LI	New paint - E		Depr.	Total
5 0 LU =0.00 EUR				50 %	



www.vabfleetservices.be Date: 24/07/2017 4/5

Pieces									
Number	Code	Description	Unit price	Depr.	Total				
5 1	WHEEL CAP		24.00 EUR	50 %	24.00 EUR				
Number	Code	Description	Unit price	Depr.	Total				
5 1	WHEEL CAP		24.00 EUR	50 %	24.00 EUR				

1	2	3	4	5	6	7	8	9	10
57.35	169.44	18.74	58.80	48.00	0	0	0	0	0
57.35	84.72	18.74	58.80	24.00	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
352.33		0	217.44	134.89
243.61	NA Deprec.		BG: 1	HOG: 0
l	0.00%			
243.61	TOTAL			



www.vabfleetservices.be Date: 24/07/2017 5/5

[x] = Status Modification

Pictures: No

**CIRCUMSTANCES** 

NORMAL CONCLUSION

Extra Time :	0 min	Waiting time :	0 min		Towing time :	0 min
		Reason:			Reason:	
NOT EXECUTED:	No	•				
Reason :						
Remark :						
Prices in EUR with	out VAT					
Authorized by customer :				Executed by VAB Fleet Se	rvices	
customer.						
Remark authorized cust	omer •					
Remark authorized cust	omer .					
Date :	24/07/2017	Hour:				
Company :						
Executed by VAB Fleet Services						
E-Mail :	@					
Signature authorized by c	ustomer					
×						