

www.vabfleetservices.be Date: 25/07/2017 1/4

C2E5AG

[X] EFFECTIVE [] NOT EXECUTED [] COLLECTION [] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 130896 KM File nr. : Mileage start / arrival: 0 / 01422759 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1DQC305 / WVWZZZ3CZDP003530 / E-File nr. : First registration: 19/07/2012 Color: VFS-nr.: **BROWN** Make + Model : Fuel type : VOLKSWAGEN / PASSAT **DIESEL** Object nr. : Fuel: Classification: **Environment Class:** EURO 5 Customer company: Co2: KBC VERZEKERINGEN NV 114g/km Driver : Remote controls: 2 TISSUE Covering: Number keys: 2[x]Vehicle kind: **VEHICLE** Seats (minivan): 0 Vehicle type: PASSAT BER Comfortline BMT 105PK Country registration: **BELGIUM**

VAT over the margin - car:	No	Metallic paint:	Yes				
Variant car:	BERLINE	Engine size:	1598				
Gear box:	Manueel	Number of places:	5				
Number of gears:	6	Number of doors:	4				
нр:	105	kW:	77				
Fisc HP		Imported vehicle:					
Animals transported:	No	Smoked in vehicle:	No				
Due date vehicle inspection:		Extra set of tires:	No				
		Use:	Unknown				
General condition:							



25/07/2017 Date: www.vabfleetservices.be 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest:	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Fro	nt tvre		215			4	55		R		16	W	
		[x]	Width			He	ight		Туре		Rim	Index	
Wheel RES:	[x]		Tyre :		OK		/	Rim :		/	Hubcap :		
			T.		017		,	ъ.		,	** 1		
Wheel RR:	[x]	FIRES	STONE Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:		
Wheel FR:	[x]	FIRES	STONE Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	Hubcap:		
Wheel RL:	[x]	FIRES	STONE Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:		
Wheel FL:	[x]	FIRES	STONE Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:		\Box

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	W
Rear tyre	215	55	R	16	W

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

 [x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 25/07/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)

[x] ROOF STYLE/FRONT/LEFT/CENTER CHIPS

[x] BONNET/CENTER/LEFT DENT

[x] BONNET/CENTER/RIGHT DENT

[X] FRONT MUDGUARD/RIGHT/FRONT OTHER DAMAGES VLEK

Interior

[x] DOOR IN REAR RIGHT

CARVED

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 0		NA Deprec. 0

0.00% TOTAL



www.vabfleetservices.be Date: 25/07/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUM	STANCES		NORMAL CONCLUSION					
Extra Time :	Extra Time: 0 min Waiting time: 0 min Reason:) min	Towing time : Reason :	0 min			
NOT EXECUTEI Reason :	D: No	I		.				
Remark :								
Prices in EUR	without VAT							
Authorized by customer :			Executed by V	AB Fleet Services				
Remark authorize	ed customer :							
Date :	25/07/2017	Hour: 15:42						
Company : Executed by VAB Services	Fleet							
E-Mail:	@							
Signature authorize	ed by customer							